

# 2011 Annual Noxious Weed Monitoring Report

---

## El Dorado Hydroelectric Project FERC Project 184



**January 2012**

Prepared for:



2890 Mosquito Road  
Placerville, CA 95667

Prepared by:



1024 Simon Drive, Suite H  
Placerville, CA 95667

# 2011 Annual Noxious Weed Monitoring Report

El Dorado Hydroelectric Project



El Dorado Irrigation District

January 16, 2012

Prepared by  
EN2 Resources, Inc.

*Cover Photos: Effective treatment at Forebay Reservoir, occurrence L04-09 in 2010 (left) and 2011 (right).*

## TABLE OF CONTENTS

1.0	Introduction.....	1
2.0	Methods.....	2
3.0	Results and Discussion .....	3
3.1	Project Facilities.....	5
3.2	Licensee-maintained roads.....	11
3.3	Priority List for Future Treatments .....	13
4.0	Summary .....	18
5.0	Recommendations.....	19
6.0	References.....	20

### List of Tables

Table 1 – Summary of Noxious Weeds Observed in the 2011 Survey

Table 2 – Summary of Noxious Weeds Observed at Project 184 Facilities in 2011

Table 3 – Summary of Noxious Weeds Observed Along Licensee-maintained Roads in 2011

Table 4 – Priority List of Point and Area Occurrences

Table 5 – Priority List of Linear Occurrences

### List of Appendices

Appendix A – Figures

    Figure 1 – Regional Location and Vicinity

    Figure 2 A, B & C – Noxious Weed and Rare Plant Occurrences: 2011 Survey – FERC  
        Project 184

Appendix B – Noxious Weed Occurrence Photos

Appendix C – Noxious Weed Occurrence Data Sheets

Appendix D – Eldorado National Forest Noxious Weed List

## 1.0 Introduction

This 2011 Noxious Weed Monitoring Report (Report) has been prepared to meet the requirements of El Dorado Irrigation District's (EID) "El Dorado Hydroelectric Project (Federal Energy Regulatory Commission (FERC) No. 184): A Plan for the Prevention and Control of Noxious Weeds" (Plan) (EID 2008a). The Plan was prepared pursuant to U.S. Forest Service 4(e) condition No. 44 of the FERC license and approved by the Eldorado National Forest (ENF) on April 17, 2007 and by FERC on May 1, 2008. Figure 1 in Appendix A shows the regional location of the survey area.

The Plan describes an annual monitoring program to identify occurrences of noxious weeds and evaluate whether existing occurrences have been controlled. The monitoring program utilizes ENF standardized monitoring forms and includes Global Positioning System (GPS) mapping of occurrences. An annual report that includes the following information is due to ENF by January 15 of each year:

- Follow-up inspections of previously identified noxious weed populations;
- Presence of any new weed populations; and
- Updated Geographic Information System (GIS) base map with the results of on-going monitoring.

Baseline data was collected in 2008 during the initial survey following the protocols of the Plan. All of the occurrences documented in surveys from 2008 through 2010 were re-visited in 2011 and evaluated in this Report. Any new occurrences observed along licensee-maintained roads or at project facilities were also recorded. Weed treatments and effectiveness are noted and evaluated in the Report, where applicable. Treatments were made in accordance with the Project No. 184 Integrated Pest Management Plan, which addresses pesticide use at EID facilities under the jurisdiction of the USFS.

The existing facilities covered under the FERC license and subject to noxious weed monitoring include:

- Facilities at the four storage reservoirs (Lake Aloha, Echo Lake, Silver Lake, and Caples Lake),
- Echo Lake Conduit,
- El Dorado Diversion Dam,
- El Dorado Canal (including flumes, tunnels, and pipelines),
- Alder Creek Diversion Dam and Feeder,
- El Dorado Forebay,
- El Dorado Pipeline and Penstock,
- El Dorado Powerhouse, and
- Licensee-maintained access roads (as identified later in this Report in Table 3).

This Report summarizes the noxious weed occurrences located within the Project 184 boundary and along licensee-maintained roads during the 2011 monitoring season and will be filed with FERC by March 1, 2012.

## 2.0 Methods

Due to the unusually cool and wet spring of 2011, field monitoring began on June 22, 2011, at the lower elevation sites and was completed on August 25, 2011 following surveys along the Echo Conduit. In accordance with the Plan, digital photos were taken (Appendix B), GPS data was collected, and standardized data forms were completed for each identified infestation (Appendix C). In most instances, GPS locations were captured using a Leica GS20 hand-held, sub-meter-accurate GPS unit with an external antenna or a Trimble Nomad with 1-3 meter accuracy. Where conditions did not allow for accurate GPS data capture, locations were approximated using existing maps and aerial photography. Most locations were captured with the GPS and a point or line was sufficient to show the location. Weeds were identified using information from *Weeds of the West, Weeds of California and Other Western States* (Volumes 1 and 2), *USDA PLANTS Database* and *CalFlora* (Whitson 1996, DiTomaso and Healy 2007, USDA 2011). Weeds located within the Project area are listed in Table 1.

Access roads covered under the FERC License were monitored by walking each road and scanning areas adjacent to both sides of the road for incidents of target weed species. The Project 184 facilities listed in Section 1 were surveyed by walking the extent of each facility. At each reservoir, areas where Project-related activities occur or have occurred were surveyed. Occurrences of both "List A" and "List B" Noxious Weeds, as defined on the ENF List of Noxious Weeds (Appendix D), were recorded on ENF data forms found in the Plan and representative photographs were taken. Tables 2 and 3 provide a summary of the noxious weeds located at each facility and along each road. The approximate size of each infestation was estimated by field staff using pacing and/or measurements from the GPS (for linear occurrences).

All GPS data was post-processed using base station data to correct for inaccuracies inherent in non-processed GPS data. This data was exported into a GIS (ESRI ArcMap version 10.0) in NAD83, California State Plane Zone 2 coordinates and rectified, as needed for mapping purposes. Maps depicting each delineated noxious weed occurrence (as defined above) are included in Appendix A (Figure 2). Digital photos and data sheets are included in Appendix B and C, respectively. The MAP ID label found in Tables 4 and 5 and in the top right corner of each data sheet corresponds to the label of each occurrence on Figure 2. The labeling protocol follows the format: 01-08 for points and L01-09 for linear features; the "L" before the number refers to "linear". The number following the dash (-08) refers to the year that each occurrence was identified. Digital photos are organized by date and photo number, corresponding to the photo log from each set of data sheets.

Coordinates for each of the point features are included in Table 4. A description of each occurrence is found on the data sheets along with an update that refers to changes in the occurrence (e.g., reduced density and/or treatment effectiveness) from 2010 to 2011. The data sheets found in the Noxious Weed Plan were adapted to Microsoft Excel spreadsheet format and the data from the field was entered into these sheets for easier reading and archiving.

This survey identifies locations of multiple plants forming a unit that can be targeted for control. General observations were recorded if scattered individual weeds were present along a road or near a facility. These observations can serve as a reference for future surveys to determine if these scattered individual weeds are forming groups that need to be controlled.

### **Mapping High Priority Species**

Based on input from the USFS and EID, EN2 created maps showing 2010 occurrences of USFS, List A noxious weed species (excluding ripgut brome and cheatgrass) and two list B species (Himalayan blackberry and sweet clover) at a scale similar to the EID Canal Atlas to enable EID to plan treatments in 2011. EN2 has prepared a similar map for the 2011 occurrences for EID to use in planning 2012 treatments.

## **3.0 Results and Discussion**

Detailed data for each occurrence is included in the data sheets found in Appendix C of this report. Table 1 summarizes the species of noxious weeds observed during the 2011 survey and whether they are “List A” or “List B” species. There were no new species observed in 2011. List A weeds are species that have been designated as a higher priority for control. Tables 2 and 3 summarize the weeds found at each facility and along the Project 184, EID-maintained roads, respectively. The details of the occurrences are summarized in Section 3.1 and 3.2.

**Table 1. Summary of Noxious Weeds Observed in the 2011 Survey**

	<b>Species</b>	<b>Common Name</b>	<b>Abbreviation*</b>	<b>Cal-IPC rating<sup>1</sup></b>
<b>List A</b>	<i>Aegilops triuncialis</i>	barbed goatgrass	AETR	High
	<i>Bromus tectorum</i>	cheat grass	BRTE	High
	<i>Centaurea solstitialis</i>	yellow starthistle	CESO3	High
	<i>Chondrilla juncea</i>	rush skeletonweed	CHJU	Moderate
	<i>Cytisus scoparius</i>	Scotch broom	CYSC4	High
	<i>Taeniatherum caput-medusae</i>	medusahead grass	TACA8	High
<b>List B</b>	<i>Bromus diandrus</i>	ripgut brome	BRDID2	Moderate
	<i>Cirsium vulgare</i>	bull thistle	CIVU	Moderate
	<i>Hirschfeldia incana</i>	short pod mustard	HIIN3	Moderate
	<i>Hypericum perforatum</i>	Klamath weed	HYPE	Moderate
	<i>Leucanthemum vulgare</i>	ox-eye daisy	LEVU	Moderate
	<i>Lathyrus latifolius</i>	perennial sweet pea	LALA4	No List
	<i>Melilotus officinalis</i> **	yellow sweet clover	MEOF	No List
	<i>Rubus armeniacus</i>	Himalayan blackberry	RUAR9	High
	<i>Torilis arvensis</i>	hedge parsley	TOAR	Moderate
	<i>Verbascum thapsus</i>	woolly mullein	VETH	Limited

\*These abbreviations are used in the tables below to indicate which species are present.

\*\* Yellow and white sweet clover are considered the same species, *Melilotus officinalis*, in the USDA PLANTS database

**<sup>1</sup>California Invasive Plant Council – Rating Definitions**

- **High** – These species have severe ecological impacts on physical processes, plant and animal communities, and vegetation structure. Their reproductive biology and other attributes are conducive to moderate to high rates of dispersal and establishment. Most are widely distributed ecologically.
- **Moderate** – These species have substantial and apparent—but generally not severe—ecological impacts on physical processes, plant and animal communities, and vegetation structure. Their reproductive biology and other attributes are conducive to moderate to high rates of dispersal, though establishment is generally dependent upon ecological disturbance. Ecological amplitude and distribution may range from limited to widespread.
- **Limited** – These species are invasive but their ecological impacts are minor on a statewide level or there was not enough information to justify a higher score. Their reproductive biology and other attributes result in low to moderate rates of invasiveness. Ecological amplitude and distribution are generally limited, but these species may be locally persistent and problematic.

### **3.1 Project Facilities**

A summary of noxious weed occurrences observed at each Project 184 facility surveyed in 2011 is presented below. The data sheets in Appendix C, along with the photos in Appendix B (photos are printed as a contact sheet and digital files are provided for better viewing), provide more detailed information about each occurrence.

**Table 2. Summary of Noxious Weeds Observed at Project 184 Facilities in 2011**

<b>Project 184 Facility</b>	<b>Noxious Weeds List A<sup>1</sup></b>	<b>Noxious Weeds List B<sup>1</sup></b>
Lake Aloha	None	None
Echo Lake	None	None
Silver Lake	None	VETH, CIVU
Caples Lake	None	VETH, MEOF, HYPE
Alder Creek Diversion Dam and Feeder	BRTE	None
Echo Lake Conduit	None	None
El Dorado Diversion Dam	CESO3, BRTE,	LALA4, CIVU, VETH, LEVU, HIIN3
El Dorado Forebay	CYSC4	RUAR9, LALA4, VETH, HYPE, CIVU
El Dorado Canal		
<i>Beat 1</i>	CHJU, BRTE, CESO3,	LEVU, HYPE, VETH, LALA4, BRDID2
<i>Beat 2</i>	BRTE	CIVU, RUAR9
<i>Beat 3</i>	None	LALA4, RUAR9, CIVU, TOAR
<i>Beat 4</i>	None	LEVU, LALA4, HYPE, CIVU, RUAR9
<i>Beat 5</i>	BRTE	LALA4, HYPE, MEOF, CIVU, VETH
<i>El Dorado Tunnel</i>	BRTE	MEOF, HYPE
<i>Lower Penstock</i>	CHJU, BRTE	RUAR9, HYPE, VETH
<i>Upper Penstock</i>	AETR, CESO3	RUAR9, CIVU, LALA4, HYPE, TOAR

<sup>1</sup>A designation of none means none of the ENF noxious weeds were present.

### Lake Aloha

Lake Aloha was surveyed on August 18, 2011. The lake is within Desolation Wilderness at approximately 8,000 feet. The areas around the auxiliary dams, the main dam, and other areas where work has occurred as part of Project 184 were all surveyed. No incidences of noxious weeds were observed during the 2011 survey and no occurrences have been observed since surveys began in 2008.

### Echo Lake and Echo Conduit

Echo Lake and the Echo Conduit were surveyed on August 25, 2011. The parking lot, dam area, and road down to the store and boat ramp were surveyed on foot. The entire conduit, including the piped and open ditch sections, up to the outlet into the creek, was surveyed. The survey involved walking along the conduit and observing the maintained area immediately adjacent to the conduit for noxious weeds. No incidences of noxious weeds were observed during the survey and no occurrences have been observed since surveys began in 2008.

### Caples Lake

Caples Lake was surveyed on August 10, 2011. Facilities surveyed include both dams, the parking area near the overflow spillway, the area around the Quonset hut, the Woods Creek Fishing Access parking area, and the new boat launch area and access road. As in prior years, a few individual wooly mullein plants were observed near the dam and overflow channel on the west side of the lake; however, these plants appeared to have been recently sprayed and were dying. This year we observed Klamath weed scattered across the face of the main dam, in low density <1%. It would not make sense to try and eradicate it, given the low density and presence of a wide variety of native plants mixed among the weeds.

At the Caples Spillway parking area we noted a small cluster of sweet clover within the vegetated strip between Highway 88 and the parking area. The vegetation here is riparian/wetland due to the small drainage running along the edge of the parking lot.

Since new construction has the potential to introduce new noxious weeds, the access road, day use and parking area for the new boat launch construction were given special attention. Sweet clover and wooly mullein were observed at several locations, primarily in the planting areas within and adjacent to the parking lot. These consisted of only a handful of plants in a few discrete locations within the day-use area (Points 04-11a-d), most of which appeared to have been recently sprayed. No noxious weeds were observed at the Woods Creek Fishing Access.

USFS botanist Matt Brown noted and removed several yellow starthistle plants in the area around the Caples Lake boat launch in mid-October this year. Brown requested that these facilities be checked and treated next year.

### Silver Lake

Silver Lake was also surveyed on August 10, 2011. The facilities surveyed include the dam and outlet area, the parking area and land surrounding the new boat launch area, the road and parking area for the Sandy Cove day-use area, and the area surrounding a small structure at the corner of Highway 88 and Kit Carson road leading to the Fergusson point day-use area. The very small occurrence of wooly mullein and bull thistle observed in 2008 near the small structure at the corner of Highway 88 and Kit Carson Road has been treated and the few weeds there were dying. The wooly mullein along the shore near the recently removed Kay's Resort is still present

and appears to be expanding slightly. There are scattered plants along the south side of the parking lot and a few patches adjacent to the lake with many first year plants. There were no weeds observed at the Sandy Cove day-use area or access road.

#### El Dorado Diversion Dam

The El Dorado Diversion Dam, near Kyburz, was surveyed on July 21, 2011. The facilities surveyed at this site include a short access road from Highway 50, the fish ladder and associated structures, and the gate area on the south side of the river. The site has some large areas of exposed soil and large rip rap near the fish ladder, along the north bank of the river. The two mapped occurrences at the Diversion Dam appear to have increasing weed density in 2011. While the control efforts in previous years have helped reduce the density and temporarily slowed the spread, it appears that a more concerted effort will be required at this site to eradicate the weeds.

Points 47-08 and 41-08 contain a mixture of sweet pea, yellow starthistle, mustard, cheat grass wooly mullein and ox-eye daisy, spread out primarily around the margins of the disturbed ground around the facility. Sweet pea is still the dominant weed. The weeds extend right up to the edge of the fish ladder, adjacent to the river.

#### Alder Creek Diversion Dam and Feeder

The Alder Creek Diversion Dam and Feeder were surveyed on July 29, 2011. This site begins at the Alder Creek Siphon at Camp 1 and continues along the contour toward the diversion dam, up the canyon, approximately 1 mile away. The site had recently been sprayed along the first several hundred feet, where the weeds are located. The cheat grass was still present and had already set seed by the time sprays were completed. It is scattered and patchy, comprising 1-5% of the herbaceous cover.

#### El Dorado Forebay

The reservoir was surveyed on July 14, 2011. The areas surveyed include the dam and dam face; the parking and day-use area; and the grounds around the south side of the reservoir from the point where the canal enters the reservoir to the point where the canal exits the reservoir. A large occurrence, Area 1, begins at the toe of the dam on the north end of the reservoir. There is a significant infestation of Himalayan blackberry with perennial sweet pea interspersed throughout. The overall size of the area infested is approximately 0.25-0.33 acre, with the weeds comprising approximately 35% of the total area. Sweet pea extends up the north side of the dam in patches up to the top of the dam and has increased since last year.

This year, because of some recent ground disturbing work near the dam, starthistle has been introduced and barbed goatgrass has spread up the gravel/dirt access road that leads from the top of the dam down the north side of the dam to the penstock exit. Black mustard was also noted in abundance along the top of the dam. The use of herbicides near sensitive areas (wetland area) of this infestation is not recommended, but higher up on the dam herbicides could be used.

In the day-use area there is still a small infestation (1-5% of the cover) of perennial sweet pea between Forebay Road and the parking area and the Klamath weed (46-08) that was there last year is gone. The weed density has been reduced since last year due to targeted control efforts. Just to the east of the parking area, between Forebay Road and the reservoir, there is a small group of scotch broom, a "List A" species (L06-08). This occurrence was targeted this year with

physical methods and possibly herbicides resulting in good control. There were still a few small seedlings; these seedlings and the cut shrubs will have to be monitored and treated again.

The linear infestations along the northeast shore of the reservoir, L04-09 and L05-09, are still present but treatments this year have reduced the density. However, a new line was added to the shoreline to reflect the spread of weeds along the shoreline. The primary weeds observed here in 2011 were Himalayan blackberry, Klamath weed and ox-eye daisy; however, wooly mullein, bull thistle and sweet pea are scattered throughout these areas as well. The blackberry is very dense in places along the shore and is mixed with native blackberry. We noted that much of the northern shoreline contained scattered ox-eye and it was visible across the reservoir along the south shore. Because of the proximity to the reservoir, these occurrences may best be controlled through physical means. Herbicides may be effective; however, there may be limited opportunity to apply herbicide because of the proximity to the lake.

#### El Dorado Powerhouse

The powerhouse, located at the terminus of the Penstock along the South Fork American River, was surveyed on June 22, 2011. There are occurrences of Himalayan blackberry, sweet clover, and wooly mullein along the road near the powerhouse (09-08). The overall extent is relatively minor and appears very similar to the extent in 2008 and 2009. Given the proximity to the river and the potential for herbicides to enter a major waterway, special care should be taken when controlling this occurrence. On the west side of the powerhouse, leading up to the penstock trail, there is a dense patch of sweet clover and wooly mullein that has increased in density this year but not overall extent. Just above the powerhouse, along the lower penstock, there is a significant amount of Himalayan blackberry that has been there since 2008.

#### El Dorado Canal

##### *Beat 1*

This portion of the canal was surveyed on July 21, 2011. Beat 1 extends from the El Dorado diversion dam down to the Alder Creek Siphon at Camp 1 and includes large areas affected by the Cleveland Fire. Overall, it appears that many occurrences in this section are rebounding following a couple of good control years. Two minor noxious weed occurrences near Carpenter Creek, identified in 2008, include ox-eye daisy and Klamath weed. One of these, point 40-08, appeared eradicated in 2009, but has since returned, although it has not spread significantly. The minor occurrence of Klamath weed near an un-named creek just east of 30-Milestone access road (10-09) was nearly controlled and only a few plants remain. A small new occurrence of Klamath weed was mapped in 2010 (06-10) near a short tunnel that the canal passes through. It has not been treated and appeared about the same but slightly denser in 2011.

The next two occurrences are in the burned area and have included two “List A” species, rush skeletonweed and starthistle scattered in a strip along the canal bench. The “List A” weed density at both of these locations had been significantly reduced as a result of treatments since 2008; however, both starthistle and rush skeleton weed are coming back along the canal. Cheat grass is still present, within the canal bench and outside the fenced area along the canal. A trend of increased wooly mullein density continues this year, with heavy infestations outside the fence, especially along L35-08, L34-08 and L33-08; L33-08 was extended approximately 300 feet east due to weed spread in 2010 and 2011. One new occurrence of wooly mullein was recorded along Beat 1 (L10-11).

*El Dorado Tunnel*

This short stretch of canal lies between the Alder Creek Siphon and the El Dorado Tunnel. In 2008, there were significant numbers of sweet clover and Klamath weed, especially near the gate. Weed control treatments have significantly reduced the density of weeds along this section in 2009 and 2010. We noted that the area did not appear to be treated in 2011. Weed density was still low but wooly mullein and cheat grass were increasing.

*Beat 2*

Beat 2 was surveyed on July 7, 2011. This is a very short stretch of canal between the Mill-Bull Tunnel and the Plum Creek Siphon. One incident of cheat grass has been identified around the facilities where the canal enters the Plum Creek Siphon (09-09). This occurrence appeared the same as last year. In 2011 a new occurrence of Himalayan blackberry was recorded below the recently rebuilt flume. This is a small patch, which should be targeted next year to catch it before it spreads too much (02-11).

*Beat 3*

Beat 3 was surveyed on July 7, 2011. This section of canal begins at the outlet of the Plum Creek Siphon at Camp X and ends at the outlet of the Esmeralda Creek Tunnel. This section of canal previously had eight mapped occurrences, most of which are Himalayan blackberry and sweet pea. Two of the occurrences include ox-eye daisy as well. Four occurrences, L18-08, L19-08, 28-08, and 29-08 are all near Ogilby Creek and all are fairly close together and contain the same mixture of blackberry and sweet pea. These 4 occurrences were combined into 1 linear occurrence because of their proximity and similar weed make-up (L06-11). Herbicide treatments between 2008 and 2011 along the canal have significantly reduced the density of weeds at these locations but the weeds are returning in some places, overall good control was observed. Caution should be used when treating these occurrences due to their proximity to the creek.

Blackberry at 26-08 has been almost completely eradicated. A new linear occurrence of hedge parsley along the canal bench (L05-11) was recorded this year. This is a minor occurrence but it should be noted that Torilis arvensis appears to be spreading throughout the project where it has been observed in the past. It should also be noted that we have observed an increase in this weed throughout the El Dorado County region.

*Beat 4*

Beat 4 was surveyed on June 29, 2011. This section of canal begins at the outlet of the Esmeralda Creek Tunnel and ends where the canal crosses under Highway 50. Few active occurrences of noxious weeds were present in this portion of the canal. Near Esmeralda tunnel and there are a couple of locations that include ox-eye daisy, Klamath weed, bull thistle and blackberry. Several occurrences, L10-08, L11-08, and 17-08 have been completely controlled by herbicide treatments along the canal since 2009 and remained eradicated in 2011.

*Beat 5*

Beat 5 was surveyed on June 29, 2011. This section of canal begins where the canal crosses Highway 50 and ends at Forebay Reservoir. Five locations with noxious weeds were mapped in 2008, no additional sites were mapped in 2009, 3 new locations were mapped in 2010 (01-02-, and 03-10) and 2 new locations were recorded in 2011 (01-11 and L04-11). The new locations

include a small patch of sweet pea and bull thistle near spillway 44 and low density sweet pea and sweet clover along the bench of the recently repaired area near Flume 51.

Near Camp 5 there remains a large amount of sweet pea along the fences around the yard and extending down to the canal in a few places (L09-08). The weeds along the canal have been greatly reduced since 2009, but there are still some very dense patches of sweet pea between the canal and the Camp 5 facility.

There are two very weedy areas along two separate access roads leading down to the canal. One is near Camp 5 (L8-08) and contains a mixture of sweet clover, wooly mullein, sweet pea, and bull thistle, among a variety of other weeds. The weeds have increased significantly here along the entire road. The second, similar occurrence (L07-08) containing bull thistle and sweet clover is located along an access road near the canal just before Bullion Bend; this occurrence has been treated and only a small amount of bull thistle remains. At point 03-10 a small patch of barbed goatgrass, a List A species, was observed in 2011.

#### *Upper Penstock*

The upper penstock, extending from Forebay Reservoir to the surge chamber, was surveyed on June 22, 2011. A total of six occurrences were mapped along this portion of the penstock. The most significant, high priority area of noxious weeds identified near the beginning of the penstock at Forebay to the Forebay Road undercrossing was treated and most of the barbed goatgrass was dead. There were still other weeds in the area to the south of the penstock between the 2 access roads.

Several other areas of sweet pea, Himalayan blackberry, bull thistle, and Klamath weed were documented between Forebay Road and the tunnel. These areas were treated between 2009 and 2010, achieving partial control of the weeds in these areas; however, the weeds were still present, especially sweet pea, which was abundant. Some of the weed infestations along the penstock (south side) extend outside the maintenance responsibility of EID.

Site L2-09, located west of the tunnel, is a low priority site that has not been treated since it was first noted in 2009. This is a long line of very scattered, low density Klamath weed. This year hedge parsley was also observed scattered throughout the same location.

Two new areas were recorded this year, one small area of ox-eye and another area that included starthistle and a few barbed goatgrass. The second site was near the big dip in the penstock where the road has recently been repaired.

#### *Lower Penstock*

The lower penstock, surveyed on July 14, 2011 refers to the section of penstock between the surge chamber and the powerhouse. The site is very steep and exposed along a northwest facing slope. A total of three occurrences are mapped along this portion of the penstock. Most weeds are located along the lower third of this section of penstock. The lower quarter of the lower penstock was sprayed in 2011, reducing the density of weeds. Klamath weed, cheatgrass, rush skeletonweed, blackberry and wooly mullein are scattered throughout of this section (L1-09), increasing up slope. The blackberry has been significantly reduced; however, near the upper portion of this line all the other weeds are increasing, especially skeletonweed.

The patch of blackberry at point 11-08 has also been treated and is 90% gone. A new linear occurrence (L07-11) was mapped this year, extending from 11-08 up slope to the 2nd penstock foundation block. Of primary concern is the increasing skeletonweed.

### **3.2 Licensee-maintained roads**

A summary of noxious weed occurrences observed along Project 184 licensee-maintained roads surveyed in 2011 is provided below. The data sheets in Appendix C, along with the photos in Appendix B (photos are printed as a contact sheet and digital files are provided for better viewing), provide more detailed information about each occurrence.

A total of 14 roads had some noxious weeds, but most were relatively minor occurrences. Six roads have “List A” noxious weeds, primarily cheatgrass, but medusa-head grass and star thistle are also present at the El Dorado Tunnel and Camp P roads, respectively. Himalayan blackberry is abundant along some roads, such as the Powerhouse Road and Highway Cut Road. Treatment along these roads significantly reduced the blackberry in places in 2009, but the blackberry is returning and additional treatments are necessary.

El Dorado Irrigation District  
2011 Annual Noxious Weed Monitoring Report

**Table 3. Summary of Noxious Weeds Observed Along Licensee-maintained Roads in 2011**

Road #	Road Name	Length	Noxious Weeds A <sup>1</sup>	Noxious Weeds B <sup>1</sup>	Control <sup>2</sup>
11N05A	Echo North	0.2	None	None	N/A
11N05D	Echo Loop	0.2	None	None	N/A
10N23Y	Caples Aux. Dam	0.11	None	VETH, MEOF	None
R41	Woods Creek	0.19	None	None	N/A
R42	Caples Main Dam	0.16	None	HYPE (noted in 2011)	None
*New	Caples Boat Launch		None	MEOF, VETH	Partial
R44	Caples Quonset	0.06	None	None	N/A
R61	30 Milestone Spur	0.01	None	None	N/A
R71**	Flume 39/40	0.42	N/A	N/A	N/A
R72	Camp X	0.56	None	None	N/A
R73	Camp 2	0.54	BRTE	BRDID2	None
R74/74A	El Dorado Tunnel	0.66	BRTE, TACA8	MEOF, HYPE, TOAR, LALA4, VETH, BRDID2	Partial
R75/75A	Camp 1	0.53	BRTE	CIVU, MEOF, HYPE, LALA4, BRDID4, TOAR, VETH	Partial
R76	Camp S	0.1	N/A	N/A	N/A
10N08Y	Bull Creek	0.43	None	None	N/A
10N08YA	Camp Two	0.79	None	CIVU, RUAR9	None
11N02Y	El Dorado Ditch Access	0.91	None	RUAR9, HYPE, CIVU	None
10N440G	Highway Cut	1.66	None	RUAR9, LALA4, CIVU, HYPE,	Partial
R81	Flume 47B	0.07	None	None	N/A
R82	Pacific Tunnel	0.24	None	None	N/A
R821	Hazel Creek Tunnel	0.18	None	MEOF	None
R83	Spillway 33	0.28	None	RUAR9, VETH, CIVU	None
R84	Old Camp 4	0.28	None	None	N/A
R87***	Camp 3	0.21	BRTE	TOAR, LALA4, RUAR9	Partial
R88	Camp P	1.32	BRTE	TOAR, CIVU, MEOF, HYPE, LALA4, VETH	Partial
R89	Rock Crusher	1.16	BRTE	MEOF, CIVU	Partial
10N40N	El Dorado Ditch Loop	0.23	None	CIVU	None
12N34H	Powerhouse	2.86	None	RUAR9, LALA4, CIVU, HYPE, MEOF, VETH	Partial
R91	Moon Lane	0.31	None	None	N/A
R92	Moon Lane East	0.2	None	None	N/A
R93	Kodiak Trail	0.21	None	HYPE	None
R94	Bend Court	0.41	BRTE	HYPE, TOAR, RUAR9,LEVU	None
<b>Total</b>	<b>15.63</b>				

<sup>1</sup>A designation of "None" means none of the ENF noxious weeds were present.

<sup>2</sup>Herbicide or other treatment effectiveness: Partial, Eradicated, N/A (not applicable; no weeds along road), None (there was no control observed)

\*New road accessing new Caples Boat Launch Facility replaces old Caples House Road.

\*\* Flume 39/40 road was "re-opened" this year for upcoming construction and should be surveyed next year.

\*\*\* Camp 3 road appears to be incorrectly mapped in EID's TSMP GIS data.

### 3.3 Priority List for Future Treatments

This section provides a priority list to help inform future treatment efforts. All noxious weeds located within the project area are a high priority for control, but the priority list attempts to give some guidance regarding which occurrences have the greatest potential to rapidly invade new areas or significantly alter natural landscapes.

The Plan identifies general prevention and control measures and provides some guidance on prioritizing control efforts to maximize the effectiveness of available resources. The following priorities have been identified in the Plan and are ranked in order:

- Prevent the introduction of new invaders
- Conduct early treatment of new infestations
- Contain and control established infestations

In addition to the criteria described above, all occurrences have been given a priority ranking of 1 through 3, with 1 being the highest priority for control and 3 being the lowest priority. The following criteria were considered when assigning priorities:

- List A noxious weed species (excluding ripgut brome and cheatgrass) and List B species (Himalayan blackberry and sweet clover) (Appendix D)
- Ability of the species to spread
- California Invasive Plant Council (CalIPC) Ranking
- Size of the occurrence
- Location of the occurrence and potential for spread
- Density of weeds within the occurrence

Tables 4 and 5 list each occurrence, along with its assigned priority. In addition, the last column “Control” indicates the level of control achieved by previous treatments.

El Dorado Irrigation District  
2011 Annual Noxious Weed Monitoring Report

**Table 4. Priority List of Point and Area Occurrences**

Collection Date	Weeds	MAP ID	X Coord.	Y Coord.	Location	Priority	Control*
6/22/2011	RUAR9, CIVU, LALA4, AETR	Area1-08			Forebay	2	No
6/22/2011	RUAR9, CIVU	01-08	6954850.36	2051734.17	12N34H	2	Moderate
6/22/2011	RUAR9	02-08	6954729.4	2051997.43	12N34H	2	Good
6/22/2011	RUAR9	03-08	6954366.54	2052317.6	12N34H	2	Good
6/22/2011	RUAR9	04-08	6953462.93	2052782.84	12N34H	2	Good
6/22/2011	RUAR9, TOAR	06-08	6952678.7	2053048.47	12N34H	2	Moderate
6/22/2011	RUAR9, HYPE, CIVU, TOAR	07-08	6953569.30	2053595.91	12N34H	2	Moderate
6/22/2011	RUAR9, HYPE, LALA4, CIVU	08-08	6954272.46	2054085.68	12N34H	2	Good
6/22/2011	RUAR9, HYPE, MEOF, VETH	09-08	6955018.74	2054018.07	Powerhouse	2	Good
7/14/2011	RUAR9, VETH, BRTE, HYPE	11-08	6955188.65	2053066.73	L. penstock	1	Moderate
6/22/2011	KW	12-08	6961361.85	2048685.29	R93	3	No
6/22/2011	LALA4, RUAR9	13-08	6963202.58	2046813.86	U. penstock	2	Moderate
7/14/2011	BRTE	14-08	6971492.55	2043707.46	Bend Ct.	2	No
6/29/2011	LEVU, LALA4	17-08	6985525.52	2039178.79	Canal - 4	2	Complete
6/23/2011	RUAR9	18-08	6986373.03	2040323.36	10N40G	2	No
6/23/2011	RUAR9	19-08	6986740.71	2040777.22	10N40G	2	No
6/23/2011	RUAR9, LALA4	20-08	6987091.28	2040986.55	10N40G	2	No
6/23/2011	RUAR9	21-08	6987696.98	2040910.37	10N40G	2	Poor
6/23/2011	RUAR9	22-08	6988102.93	2040756.85	10N40G	2	Poor
6/23/2011	RUAR9	24-08	6989867.32	2042125.28	10N40G	2	No
7/7/2011	CIVU	25-08	6991666.38	2042720.19	10N40N	2	Good
7/7/2011	RUAR9	26-08	6997324.69	2043108.91	Canal - 3	2	Good
7/1/2011	MULTIPLE	29-08	6997871.66	2043793.63	R88	1	Good
7/1/2011	TOAR	30-08	6997715.6	2044783.6	R88	2	Moderate
7/1/2011	TOAR	31-08	6998069.87	2045590	R88	2	Good
7/1/2011	TOAR, CIVU	32-08	6998807.15	2045932.01	R88	2	Good
7/1/2011	LALA4, RUAR9	33-08	6999613.1	2046520.61	Canal - 3	2	Good
7/1/2011	HYPE, CIVU	34-08	7000965.97	2044277.99	Road	3	Good
7/21/2011	BRTE, MEOF	36-08	7024182.79	2044078.51	R74	2	Complete
7/21/2011	BRDID4, BRTE MEOF	37-08	7024476.75	2044556.35	R75	2	Moderate
7/21/2011	LALA4	38-08	7025143.3	2044421.83	Canal - 1	3	No
7/21/2011	BRTE, MEOF	39-08	7025260.04	2044718.29	R75	2	Good
7/21/2011	LEVU, VETH	40-08	7038988.85	2043926.52	Canal - 1	3	No
7/21/2011	LALA4	41-08	7040924.83	2044986.97	Diversion D.	1	No

El Dorado Irrigation District  
2011 Annual Noxious Weed Monitoring Report

8/10/2011	CIVU, VETH	44-08	7097977.02	2011316.78	Silver L.	3	Good
6/29/2011	LALA4	45-08	6967150.56	2044448.8	Canal - 5	2	Good
7/14/2011	LALA4, HYPE	46-08	6965365.41	2045946.49	Forebay	3	Good
7/21/2011	MULTIPLE	47-08	7040985.84	2045030.6	Diversion D.	1	No
7/21/2011	LEVU	48-08	7038113.23	2044064.46	Canal - 1	2	No
8/10/2011	VETH	49-08	7113897.88	2023827.66	Caples L.	3	Good
7/7/2011	LEVU	50-08	6992607.94	2042172.70	Canal - 4	3	No
6/22/2011	RUAR9	01-09	6952562.95	2050890.11	Road	3	Good
7/14/2011	MEOF	02-09	6957365.66	2051364.58	Surge	3	Good
6/23/2011	RUAR9	04-09	6985158.77	2038541.74	11N02Y	3	No
7/7/2011	RUAR9, LEVU	05-09	6992804.44	2042087.23	Canal - 4	3	Good
7/7/2011	CIVU	06-09	7005496.18	2042673.45	Canal - 3	3	No
7/1/2011	BRTE	07-09	7009298.52	2042163.42	R73	2	No
7/1/2011	CIVU, RUAR9	08-09	7010098.66	2039555.01	10N08Y	3	No
7/7/2011	BRTE	09-09	7007523.92	2044300.18	Plum Siphon	2	Moderate
7/21/2011	HYPE	10-09	7035021.59	2043971.73	Canal - 1	3	Good
8/10/2011	VETH	11-09	7097898.36	2010048.13	Silver L.	2	No
6/29/2011	VETH	01-10	6968322.05	2043543.66	Canal - 5	3	Good
6/29/2011	BRTE	02-10	6971379.14	2044469.72	Canal - 5	2	Moderate
6/29/2011	BRTE, MEOF, AETR	03-10	6973005.33	2044972.35	Canal - 5	1	No
6/29/2011	HYPE, MEOF, CIVU	04-10	6988383.42	2039170.51	Canal - 4	2	No
6/23/2011	VETH, CIVU, RUAR9	05-10	6988457.26	2040717.33	10N40G	2	No
7/21/2011	HYPE	06-10	7031943.32	2043584.48	Canal - 1	3	No
6/29/2011	LALA4, CIVU	01-11	6974408.58	2045422.55	Canal - 5	3	No
7/7/2011	RUAR9	02-11	7008652.83	2044409.19	Canal-2	3	No
8/10/2011	MEOF	03-11	7113510.72	2023811.33	Caples L.	3	No
8/10/2011	MEOF	04-11a	7120177.39	2024772.45	Caples L.	2	Good
8/10/2011	MEOF	04-11b	7120044.62	2024630.86	Caples L.	2	Good
8/10/2011	MEOF/VETH	04-11c	7119938.93	2024752.34	Caples L.	2	Good
8/10/2011	VETH	04-11d	7119984.54	2024563.12	Caples L.	2	Good

\*Values could be: Complete, Good, Moderate or No (no weed control observed).

El Dorado Irrigation District  
2011 Annual Noxious Weed Monitoring Report

**Table 5. Priority List of Linear Occurrences**

Collection Date	Weeds	Length (ft.)	MAP ID	Location	Priority	Control*
6/22/2011	MULTIPLE	221	L01-08	12N34H	2	Moderate
6/22/2011	HYPE, RUAR9	504	L02-08	12N34H	2	Good
6/22/2011	RUAR9, LALA4, HYPE, CIVU	79	L03-08	U. penstock	2	Moderate
6/22/2011	RUAR9, CIVU, LALA4, BRDID4	408	L04-08	U. penstock	2	Good
6/22/2011	CIVU, LALA4, AETR, BRDID4	311	L05-08	U. penstock	1	Moderate
7/14/2011	CYSC4	98	L06-08	Forebay	1	Good
6/29/2011	CIVU, MEOF	297	L07-08	Canal - 5	2	Good
6/29/2011	VETH, CIVU, LALA4, MEOF	367	L08-08	Canal - 5	2	No
6/29/2011	LALA4	133	L09-08	Canal - 5	2	No
6/23/2011	RUAR9, HYPE, CIVU	1063	L12-08	11N02Y	1	No
6/23/2011	RUAR9, VETH, CIVU	171	L13-08	R83	2	No
6/23/2011	RUAR9, CIVU, LALA4	545	L14-08	10N40G	1	No
6/23/2011	RUAR9, CIVU, LALA4	262	L15-08	10N40G	2	Moderate
7/1/2011	MULTIPLE	940	L17-08	R87	1	Moderate
7/1/2011	RUAR9, BRTE, TOAR, LALA4	308	L20-08	R88	1	Good
7/1/2011	MULTIPLE	630	L21-08	R88	1	Good
7/1/2011	MULTIPLE	725	L22-08	R89	1	Good
7/1/2011	TOAR, CIVU	20	L23-08	R88	2	Good
7/1/2011	TOAR	64	L24-08	R88	2	Good
7/1/2011	CIVU	188	L25-08	10N08YA	3	Poor
7/21/2011	MULTIPLE	1014	L26-08	R74/74A	1	Moderate
7/29/2011	HYPE, MEOF, BRTE	225	L27-08	Canal - AC	1	No
7/21/2011	MULTIPLE	866	L28-08	R74/74A	1	Moderate
7/21/2011	MULTIPLE	741	L29-08	R75	1	Moderate
7/21/2011	LALA4 ,BRTE, HYPE, MEOF	340	L30-08	R75	2	Good
7/29/2011	BRTE	325	L31-08	Alder Crk	2	Moderate
7/21/2011	MEOF, BRTE, VETH	237	L32-08	75A	2	Good
7/21/2011	BRTE, VETH, HYPE	155	L33-08	Canal - 1	3	No
7/21/2011	BRTE, VETH	193	L34-08	Canal - 1	2	No
7/21/2011	BRTE, VETH	201	L35-08	Canal - 1	2	No
7/14/2011	RUAR9, VETH, BRTE, CHJU	418	L01-09	L. penstock	1	Moderate
7/14/2011	HYPE, TOAR	2373	L02-09	U. penstock	3	No
6/22/11	LALA4, RUAR9	141	L03-09	U. penstock	3	Good
7/14/2011	MULTIPLE	46	L04-09	Forebay	2	Moderate
7/14/2011	RUAR9, HYPE, LEVU	328	L05-09	Forebay	2	No
6/23/2011	MEOF	167	L06-09	R821	3	No

El Dorado Irrigation District  
2011 Annual Noxious Weed Monitoring Report

7/1/2011	BRDID, BRTE	1845	L07-09	R73	2	Moderate
6/22/2011	RUAR9, HYPE, CIVU		<sup>1</sup> L01-10	12N34H	2	No
6/22/2011	AETR, CESO3	85	L01-11	U.Penstock	1	No
6/22/2011	LEVU	204	L02-11	U.Penstock	3	No
6/23/2011	RUAR9	337	<sup>2</sup> L03-11	11N02Y	1	No
6/29/2011	MEOF, LALA4	284	L04-11	Canal - 5	3	No
7/7/2011	TOAR	138	L05-11	Canal - 5	3	No
7/7/2011	LALA4, RUAR9	545	<sup>3</sup> L06-11	Canal - 5	2	Moderate
7/14/2011	CHJU, HYPE, RUAR9, BRTE	560	L07-11	L. Penstock	1	No
7/14/2011	HYPE, LEVU	281	L08-11	Forebay	3	No
7/14/2011	RUAR9, TOAR, HYPE, LALA4	890	L09-11	Bend Ct.	2	No
7/21/2011	VETH	65	L10-11	Canal - 1	3	No

\*Values could be: Complete, Good, Moderate or No (no weed control observed).

<sup>1</sup>Previously identified as point occurrence 05-08. <sup>2</sup>Previously identified as point occurrences 16-08 and 03-09.

<sup>3</sup>Previously identified as occurrences L18-08, L19-08, 27-08 and 28-08.

## 4.0 Summary

Data was collected on a total of 112 weed occurrences throughout the Project 184 facilities and licensee-maintained roads in 2011. There were 10 new linear occurrences (2 of those lines were created to consolidate 6 previous occurrences) and 4 new point locations (point 04-11 is actually 4 sub-points). Due to control efforts, approximately 55% (62 of the 112 sites) of the occurrences had good or moderate control. Overall, there continues to be relatively few significant occurrences of "List A" noxious weed species.

As in 2010, "List A" weed species were observed along 7 roads and 9 facilities (Forebay, Diversion Dam, Alder Creek Feeder, and 5 sections of the Canal; Beat 1, Beat 2, Beat 5, El Dorado Tunnel, and the upper and lower sections of penstock). Several areas, however, experienced a spread of "List A" weeds. Increased starthistle and skeletonweed along Beat 1; increased skeleton weed and cheat grass along the lower penstock; two new spots of barbed goatgrass along the upper penstock and Beat 5; and Lake Aloha, Echo Lake and Echo Conduit remained free of listed weeds. Overall there doesn't appear to be major spreading of the noxious weed occurrences or increases in the incidence of new occurrences.

The most common "List A" species within the Project area is still cheat grass, followed by skeletonweed. The occurrences of starthistle and skeletonweed on Beat 1 of the canal have shown signs of increase this year. The Scotch broom at Forebay was targeted with 95% success; this site should be treated again soon to increase the effectiveness of the control. The barbed goatgrass along the upper penstock near Forebay Reservoir was also aggressively treated and mostly eliminated; however, a few new small patches of this species were observed this year (near Forebay dam, along the upper penstock and a small patch on Beat 5 between spillway 44 and 45) and will need to be monitored closely next year for signs of spread.

The most common and widespread noxious weeds in the survey area continue to be Himalayan blackberry, perennial sweet pea, sweet clover and Klamath weed.

As noted last year, wooly mullein seems to be increasing, especially along Beat 1 of the canal. 2011 was another wet and cool year so this weather pattern may be contributing to the spread of wooly mullein. Also, with the large number of plants outside the fence and therefore outside the typical treatment zone, there continues to be a large source of seed to re-inoculate the canal bench. Hedge parsley also seemed to be more prevalent this year, within the project and throughout the region as well.

Based on input from the USFS and EID, EN2 created maps showing 2010 occurrences of USFS, List A noxious weed species (excluding ripgut brome and cheatgrass) and two list B species (Himalayan blackberry and sweet clover) at a scale similar to the EID Canal Atlas t enable EID to plan treatments in 2011. EN2 has prepared a similar map for the 2011 occurrences for EID to use in planning 2012 treatments.

## 5.0 Recommendations


In 2011, the USFS and EID agreed to focus the survey on List A noxious weed species (excluding ripgut brome and cheatgrass) and two list B species (Himalayan blackberry and sweet clover). This strategy did increase the efficiency of the survey; however, this approach did not significantly reduce the area required to be surveyed each year. Therefore, EID proposes to consult with the USFS to determine if an alternate monitoring schedule can be implemented. Some potential options for consideration include:

- Survey the Project area every two years
- Divide the Project area into sections that can be surveyed in separate years

## 6.0 References

- Bosard et.al. 2000. Carla C. Bosard, John M. Randall, and Marc C. Hoshovsky. Invasive Plants of California's Wildlands. University of California Press, Berkeley and Los Angeles, CA.
- Cal-IPC 2006. California Invasive Plant Council (Cal-IPC); California Invasive Plant Inventory, Cal-IPC publication 2006-02, Berkeley, CA. Available at:  
<http://www.cal-ipc.org/ip/inventory/pdf/Inventory2006.pdf>
- Davy 2008. Josh Davy. University of California Cooperative Extension. Barb Goatgrass – Impact and Control. Website accessed, October 2008.  
<http://ucce.ucdavis.edu/files/filelibrary/827/34297.pdf>
- DiTomaso and Healy 2007. Weeds of California and Other Western States: Volumes 1 and 2. University of California Agriculture and Natural Resources Publication 3488. Oakland, CA
- EID 2003. El Dorado Relicensing Settlement Agreement. El Dorado FERC Project 184. EID.
- EID 2006. FERC Order Issuing New License – Project 184
- EID 2008a. El Dorado Hydroelectric Project (FERC No. 184); A Plan for Prevention and Control of Noxious Weeds. El Dorado Irrigation District.
- EID 2008b. Integrated Pest Management Plan. El Dorado Hydroelectric Project (FERC No. 184) and Consumptive Water Delivery Facilities on National Forest Lands. September 2008. El Dorado Irrigation District.
- ENF 2003. FS Final Terms and Conditions In Connection with the Application for Relicensing of The El Dorado Hydroelectric Project (FERC No. 184). October, 2003.
- ENF 2007 Eldorado National Forest Noxious Weed Species List. Updated 12/26/07.
- FERC 2008 Letter from FERC to EID. Order Modifying and Approving Noxious Plan Pursuant to U.S. Forest Service 4(e) Condition 44.
- Whitson et. al. 1996. Tom D. Whitson, Editor. Weeds of the West 5<sup>th</sup> ed. The Western Society of Weed Science. Newark, CA.
- USDA 2010. United States Department of Agriculture, Natural Resources Conservation Service PLANTS Database. Accessed via the world wide web, 2010 at: <http://plants.usda.gov/>

## APPENDIX A Figures



## **Figure 1. Regional Location and Vicinity**

Created By: Ethan Koenigs  
Date: 10/13/11

2011 Noxious Weed Survey  
Project 184 Roads and Facilities

0      3.75      7.5      15 Miles




Figure 2. Noxious Weed and Rare Plant Occurrences  
2011 Survey - FERC Project 184  
Page 1 of 3



Point Occurrences	Linear Occurrences
Treatment Success	Treatment Success
Complete	Complete
Good	Good
Moderate	Moderate
Poor	Poor
None	None

- Roads**
- Highway
  - Major Road
  - Licensee Maint'd Roads
  - USFS Roads
- Administrative Boundaries**
- USFS Land
  - Communities




Date: 10/13/2011 Created By: Ethan Koenigs





1 inch = 3,000 feet  
NAD 1983 State Plane California II Feet

Prepared By:







**Figure 2. Noxious Weed and Rare Plant Occurrences**  
2011 Survey - FERC Project 184  
Page 3 of 3



**Point Occurrences**

Treatment Success	Symbol
Complete	Green checkmark
Good	Green triangle
Moderate	Yellow triangle
Poor	Orange triangle
None	Red triangle

Noxious weed area

**Linear Occurrences**

Treatment Success	Symbol
Complete	Green line
Good	Yellow-green line
Moderate	Yellow line
Poor	Orange line
None	Red line


#### Legend

**Rare Plants**

Red Hills Soap Lily	Red flower icon
Yellow-burr Navarretia	Yellow flower icon
Pleasant Valley Mariposa Lily	Yellow-orange flower icon
Pacific Yew	Orange-yellow flower icon

**Roads**

- Highway
- Major Road
- - - Licensee Maint'd Roads
- - - USFS Roads
- Communities



1 inch = 3,000 feet

NAD 1983 State Plane California II Feet

Prepared By:

**ENR**  
Water and Energy  
Consulting Services  
RESOURCES, INC.

Date: 10/05/11 Created By: Ethan Koenigs

## APPENDIX B

### Noxious Weed Occurrence Photos

June 22, 2011: Upper penstock (partial); Powerhouse Rd., Forebay Res., Rd. 93



P6220621



P6220624



P6220625



P6220626



P6220627



P6220628



P6220629



P6220630



P6220631



P6220632



P6220633



P6220634



P6220635



P6220636



P6220637



P6220638



P6220639



P6220640



P6220641



P6220642



P6220643



P6220644



P6220645



P6220646



P6220647



P6220648



P6220649



P6220650



P6220651



P6220652



P6220653



P6220654



P6220655



P6220656



P6220657

June 22, 2011: Upper penstock (partial); Powerhouse Rd., Forebay Res., Rd. 93 (cont.)



P6220658



P6220614



P6220615



P6220616



P6220617



P6220618



P6220619



P6220620

June 23, 2011: Highway Cut Rd. (10N40G), Rds. 81-84, 11N02Y



P6230659



P6230660



P6230661



P6230662



P6230663



P6230664



P6230665



P6230666



P6230667



P6230668



P6230669



P6230670



P6230671



P6230672



P6230673



P6230674



P6230675



P6230676



P6230677



P6230678



P6230679



P6230680



P6230681



P6230682



P6230683



P6230684



P6230685

June 29, 2011: El Dorado Canal Beats 4 and 5



P6290687



P6290689



P6290690



P6290691



P6290692



P6290693



P6290694



P6290695



P6290696



P6290697



P6290698



P6290699



P6290700



P6290701



P6290702



P6290703



P6290686

July 1, 2011: Camp 2 and 3 roads, 10N08Y, Rds.87-89



P7010710



P7010711



P7010712



P7010713



P7010714



P7010715



P7010716



P7010717



P7010718



P7010719



P7010720



P7010721




P7010722



P7010723




P7010724



P7010725



P7010726



P7010727



P7010728



P7010729



P7010730



P7010704



P7010705



P7010706



P7010707



P7010708



P7010709

July 7, 2011: El Dorado Canal Beats 2, 3 and partial 4



P7070576



P7070577



P7070578



P7070579



P7070580



P7070581



P7070582



P7070583



P7070584



P7070585



P7070586



P7070587



P7070588



P7070589

July 14, 2011: Lower penstock, partial upper penstock, partial Forebay Res., Moon Lane, Bend Court



P7140597



P7140598



P7140599



P7140600



P7140601



P7140602



P7140604



P7140605



P7140606



P7140607



P7140608



P7140609



P7140610



P7140611



P7140612



P7140613



P7140614



P7140615



P7140616




P7140617



P7140590



P7140591



P7140592



P7140593



P7140594



P7140596

July 21, 2011: El Dorado Canal Beat 1, Camp 1 rds. (74 and 75)



P7210628



P7210629



P7210630



P7210631



P7210632



P7210633



P7210634



P7210635



P7210636



P7210637



P7210638



P7210639



P7210640



P7210645



P7210646



P7210647



P7210648



P7210649



P7210650



P7210651



P7210652



P7210653



P7210654



P7210655



P7210656



P7210657



P7210658



P7210659



P7210660



P7210661



P7210662



P7210663



P7210664




P7210665



P7210666

July 21, 2011: El Dorado Canal Beat 1, Camp 1 rds. (74 and 75) (cont.)



P7210667



P7210668



P7210622



P7210623



P7210624



P7210625



P7210626



P7210627

August 10, 2011: Caples Lake and Silver Lake



P8100728



P8100729



P8100730



P8100731



P8100732



P8100733



P8100734



P8100735



P8100736



P8100737



P8100738



P8100739



P8100743



P8100744



P8100745

**APPENDIX C**  
**Noxious Weed Occurrence Data Sheets**

**APPENDIX C****EID Weed Observation and Monitoring Form**

Powerhouse access road, Upper Penstock and other access roads

<b>Photo Log</b>			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
614	09-08	S	Good control of weeds near powerhouse; very little MEOF
615	09-08	W	Good control of MEOF and HYPE along road near powerhouse
616	09-08	W	Downslope side of road - good weed control - RUAR9 near water
617	09-08	E	Good control of RUAR9
618	08-08	W	Good control of weeds
619	07-08	SW	RUAR9
620	07-08	SW	Good control along ditch; some RUAR9 adjacent to ditch
621	07-08	W	RUAR9 - partial control
624	06-08	NE	RUAR9 - below road
625	06-08	W	Good control along road shoulder - RUAR9 just outside spray zone, below road
626	L01-10	NE	CIVU in ditch
627	L01-10	E	RUAR9 encroaching on road
628	04-08	W	Good control along road
629	04-08	W	Good control along road, RUAR9 outside of spray zone
630	03-08	NW	Good control along road
631	02-08	W	Partial control of RUAR9
<b>Notes</b>			

Photo Log			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
632	02-08	NW	Dead RUAR9
633	01-08	E	RUAR9 downslope of road
634	01-08	E	Good control of weeds along ditch
635	L02-08	W	Good control of weeds
636	L02-08	E	Very few HYPE along road; good control
637	L01-08	S	MEOF in dtich
638	L01-08	S	BRTE - along west side of road - few other weeds.
639	L01-08	N	A few MEOF with BRTE
640	01-09	W	Dead RUAR9
641	Area 01-08	SW	LALA4 and LEVU - RUAR9 in background
642	Area 01-08	S	Recent disturbance - RUAR9 clumpy
643	L05-08	W	Penstock near outlet - good control of AETR
644	L05-08	E	Patchy weeds on berm - LALA4, BRTE, LEVU
645	L05-08	W	Patchy weeds on South side berm - LALA4, BRTE, LEVU, CIVU
646	L04-08	W	Weeds along road shoulder LALA4 - good control in ROW
647	L04-08	E	Dense LALA4; RUAR9 in low area
648	L04-08	SW	Partial control - dense RUAR9
649	L03-09	SW	LALA4/ RUAR9
650	L03-09	E	LALA4
651	L03-09	S	LALA4
Photo Log			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
652	13-08	S	Clump of LALA4
653	L01-11	E	Scattered LALA4, BRTE

## Notes

Page 3

General Information		ID: 01-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Powerhouse Road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	1/4 acres	
Disturbances & impacts	Roadside maintenance	
Associated species	Douglas Fir, Big-leaf Maple, Canyon Live Oak, California Hazelnut, Giant Chain Fern	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Shady, N. facing slope	
Weed Information		Weed Identification
Weed genus and species	<i>Rubus discolor</i>	<i>Cirsium vulgare</i>
Weed common name(s)	Himalayan Blackberry	Bull Thistle (5 plants)
Presence or Absence	Present (all)	Presence
Treated	No	
Infested area	10,000 sq. ft.	
Canopy Cover	5-25%	
Appearance	New growth	Dead
Distribution pattern	Clumpy	Scattered patchy
Photo documentation	633, 634	
Weed Location		
Geographic location (ID)	01-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1-5m	At a curve in the road at a drainage. 2011 Update: Good control up/downslope. Still abundant further downslope.
Location description		

General Information		ID: 02-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Powerhouse Road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	10,000 - 15,000 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	Douglas Fir, Big-leaf Maple, Pacific Dogwood.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Shady area along/near a drainage.	
Weed Information		Weed Identification
Weed genus and species	<i>Rubus discolor</i>	
Weed common name(s)	Himalayan Blackberry	
Presence or Absence	Present (all)	
Treated	Yes	
Infested area	10,000-15,000 sq. ft.	
Canopy Cover	1-5%	
Appearance	New growth	Dead
Distribution pattern	Clumpy	Linear
Photo documentation	631, 632	
Weed Location		
Geographic location (ID)	02-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	5-15m	
Location description	Downslope of 01-08 (road switch back) near same drainage; 2 locations, separated by about 200'; another patch downslope along road - 200'. 2011 Update: Good control but still growing off the road shoulder.	

General Information		ID: 03-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011
Observer name(s)		
Site Information		
Site or facility name	Access Road	
Site address or other description	Powerhouse Road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	250 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	Douglas Fir, Big-leaf Maple, Pacific Dogwood, California Hazelnut.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)		
Weed Information		Weed Identification
Weed genus and species	<i>Rubus discolor</i>	
Weed common name(s)	Himalayan Blackberry	
Presence		
Presence or Absence	Present (all)	
Treated	Yes	
Infested area	250 sq. ft.	
Canopy Cover	<1%	
Appearance	Dead	
Distribution pattern	Clumpy	
Photo documentation	630	
Weed Location		
Geographic location (ID)	03-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	5-15m	
Location description	Downslope side of road.	2011 Update: Good control.

General Information			ID: 04-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011	
Observer name(s)	Site Information		
Site or facility name	El Dorado Powerhouse		
Site address or other description	Powerhouse Road		
Ownership	Transportation Corridor		
Land use type	Forest		
Invaded vegetation type	Roadside maintenance		
Gross Area	750	sq. ft.	
Disturbances & impacts	Douglas Fir, Big-leaf Maple, Pacific Dogwood, California Hazelnut.		
Associated species	Shady, N. facing slope		
Environmental Conditions (e.g. soil conditions, exposure, etc.)			
Weed Information			
Weed genus and species	Rubus armeniacus	Verbascum thapsus	
Weed common name(s)	Himalayan Blackberry	Woolly Mullein	
Presence or Absence	Present (not all species)	No VETH	
Treated	Yes		
Infested area	750	sq. ft.	
Canopy Cover	1-5%		
Appearance	New growth		
Distribution pattern	Clumpy	Linear	
Photo documentation	628, 629		
Weed Location			
Geographic location (ID)	04-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	5-15m		
Location description	Along road near a spur road fork. 2011 Update: Good control on both weeds.		

General Information		ID: 06-08
Collection date (mm/dd/yyyy)	6/22/2011	
Observer name(s)	Ethan Koenigs	
Site Information		
Site or facility name	Access Road	
Site address or other description	Powerhouse Road	
Ownership	Transportation Corridor	
Land use type	Forest	
Invaded vegetation type	1,000 sq. ft.	
Gross Area	Roadside maintenance	
Disturbances & impacts		
Associated species	Douglas Fir, Big-leaf Maple, Buckeye, California Bay Tree.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Shady, N-facing canyon.	
Weed Information		
Weed Identification		
Weed genus and species	<i>Rubus discolor</i>	<i>Torilis arvensis</i>
Weed common name(s)	Himalayan Blackberry	Hedge Parsley
Presence		
Presence or Absence	Present (all)	
Treated	Yes	
Infested area	500 sq. ft.	
Canopy Cover	5-25%	1-5%
Appearance	Germ'g./early growth	New growth
Distribution pattern	Linear	Clumpy
Photo documentation	624, 625	
Weed Location		
Geographic location (ID)	06-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	5-15m	Along road on downslope side, at a slight bend in the road near a minor drainage. 2011 Update: Low portion moderately controlled on downslope side. Still extensive downslope.
Location description		

General Information		ID: 07-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011
Observer name(s)	Site Information	
Site or facility name	El Dorado Powerhouse	
Site address or other description	Powerhouse Road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	1,000 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	Douglas Fir, Big-leaf Maple, Pacific Dogwood, Black Oak.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Shady, N. facing canyon	
Weed Information		Weed Identification
Weed genus and species	<i>Rubus discolor</i>	<i>Hypericum perforatum</i>
Weed common name(s)	Himalayan Blackberry	Klamath weed
		Bull Thistle
		Hedge Parsley
Presence or Absence	Present (all)	Presence
Treated	No	
Infested area	1,000 sq. ft.	
Canopy Cover	5-25%	
Appearance	New growth	Dead
Distribution pattern	Clumpy	Scattered patchy
Photo documentation	619, 620, 621, 622	
Weed Location		
Geographic location (ID)	07-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	5-15m	
Location description	Along road near a wide bend along a small drainage extending down the road for a couple hundred feet. 2010 Update: Extent appears same as 2009 with slight increase. 2011 Update: Partial control of RUAR9(sprayed). Upper occurrence has moderate control but is extensive downslope.	

General Information		ID: 08-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011
Observer name(s)		
Site or facility name	El Dorado Powerhouse	Site Information
Site address or other description	Powerhouse Road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	4,000 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	Douglas Fir, Canyon Live Oak, Black Oak & California Grape.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Shady, N. facing canyon	
Weed Information		
Weed Identification		
Weed genus and species	<i>Rubus discolor</i>	<i>Lathyrus latifolius</i>
Weed common name(s)	Himalayan Blackberry	Klamath Weed
		Perennial Sweet Pea
		Bull Thistle
Presence		
Presence or Absence	Yes	No LALA4 or CIUV
Treated		Extends down road 200' - RUAR9 downslope
Infested area	500 sq. ft.	
Canopy Cover	<1%	
Appearance	New growth	Dead
Distribution pattern	Clumpy	
Photo documentation	618	
Weed Location		
Geographic location (ID)	08-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	5-15m	Along road on downslope side; SMUD powerhouse visible; Extends down road 200' - RUAR9 downslope. 2011 Update: Still present downslope but overall good control.
Location description		

General Information		ID: 09-08		
Collection date (mm/dd/yyyy)	6/22/2011			
Observer name(s)	Ethan Koenigs			
Site Information				
Site or facility name	El Dorado Powerhouse			
Site address or other description	Powerhouse Road			
Ownership	EID			
Land use type	Transportation Corridor	Powerhouse		
Invaded vegetation type	Forest			
Gross Area	7500 sq. ft.			
Disturbances & impacts	Roadside maintenance	Facility Maintenance		
Associated species	Douglas Fir, Ponderosa Pine.			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Very exposed sunny area; many weeds among rip rap below road.			
Weed Information				
Weed Identification				
Weed genus and species	<i>Rubus discolor</i>	<i>Meliolotus alba</i>		
Weed common name(s)	Himalayan Blackberry	White Sweet Clover		
Presence				
Presence or Absence	Present (not all species)	No MEOF, VETH or HYPE		
Treated	No			
Infested area	400-600 sq. ft.			
Canopy Cover	<1%			
Appearance	New growth	Dead		
Distribution pattern	Clumpy	Scattered patchy		
Photo documentation	614, 615, 616, 617			
Weed Location				
Geographic location (ID)	09-08			
Coordinate system	Ca. State Plane Zone 2			
Datum	NAD83			
Location data accuracy	5-15m			
Location description	Along road and slope leading down to the river. 2011 Update: Overall good control, no MEOF, VETH, or HYPE.			

General Information		ID: 12-08	
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011	
Observer name(s)			
Site or facility name	Access Road	Site Information	
Site address or other description	Penstock, Kodiak Trail access road.		
Ownership			
Land use type	Transportation Corridor		
Invaded vegetation type	Forest		
Gross Area	250 sq. ft.		
Disturbances & impacts	Pipe Maintenance	Roadside maintenance	
Associated species			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Ponderosa pine, incense cedar, mountain misery Open pine forest, southeast exposure		
Weed Information		Weed Identification	
Weed genus and species	<i>Hypericum perforatum</i>		
Weed common name(s)	Klamath Weed		
Presence or Absence	Present (all)	Presence	
Treated	Yes		
Infested area	250 sq. ft.		
Canopy Cover	<1%		
Appearance	New growth		
Distribution pattern	Clumpy		
Photo documentation	657,658		
Weed Location			
Geographic location (ID)	12-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	< 1m		
Location description	On south side of Kodiak Trail near split in road; minor occurrence. 2011 Update: Small amount of HYPE coming back; few plants near gate as well.		

General Information			ID: 13-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011	
Observer name(s)			
Site or facility name	EID Penstock	Between forebay reservoir and tunnel	
Site address or other description			
Ownership			
Land use type	Water Transport Facility		
Invaded vegetation type	Forest		
Gross Area	Pipe Maintenance	700 sq. ft.	
Disturbances & impacts			
Associated species		Ponderosa Pine, mountain misery ( <i>Chameobatia foliolosa</i> ) .	
Environmental Conditions (e.g. soil conditions, exposure, etc.)		Roadside shoulder - gravelly soil -sunny	
Weed Information			Weed Identification
Weed genus and species	<i>Rubus discolor</i>	<i>Lathyrus latifolius</i>	
Weed common name(s)	Himalayan Blackberry	Perennial Sweet Pea	
Presence or Absence	Present (all)		
Treated	Yes		
Infested area		500 sq. ft.	
Canopy Cover	<1%	5-25%	
Appearance	Germ'g./early growth	New growth	
Distribution pattern	Clumpy		
Photo documentation	652		
Weed Location			
Geographic location (ID)	13-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	< 1m		
Location description	Isolated clump along Penstock road (southside). 2011 Update: In general LALA4 scattered on shoulder of road from gate near Forebay Rd. to the point 13-08. Good control on RUAR9, LALA4 looks the same.		

General Information			ID: Area1-08
Collection date (mm/dd/yyyy)	Ethan Koenigs & Chad Johnson	6/22/2011 & 07/14/2011	
Site or facility name	Forebay Reservoir		Site Information
Site address or other description	Below face of dam.		
Ownership			
Land use type	Water Storage Facility		
Gross Area	Forest		
Disturbances & impacts	0.33 acres		
Associated species	Facility Maintenance		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Ponderosa Pine, Willow, Alder, Jucus species, Carex species, Grasses, Native Blackberry.		
Wetland area			
Weed Information			
Weed genus and species	<i>Rubus discolor</i>	<i>Lathyrus latifolius</i>	Weed Identification
Weed common name(s)	Himalayan Blackberry	Perennial Sweet Pea	
Presence or Absence	Present (all)	<i>Leucanthemum vulgare</i>	
Treated	Yes	Ox Eye Daisy	
Infested area	0.33 acres	barbed goatgrass	Starthistle
Canopy Cover	25-50%	black mustard	
Appearance	New growth	flowering	1-5%
Distribution pattern	Clumpy	Scattered patchy	<1%
Photo documentation	612, 613, 641, 642	Scattered even	New growth
		Flowering	Scattered patchy
Weed Location			
Geographic location (ID)	Area 1-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	< 1m		
Location description	At the base of the dam on the north side there is a wet area and weeds surround this area. 2011 Update: Recent ground disturbance; AETR, CESO along access road leading from parking area down to Penstock; HIN extends along top of dam; Sweet pea expanding to 25-50%.		

General Information		ID: L01-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Powerhouse Road	Section of road beneath transmission lines.
Ownership	Transportation Corridor	
Land use type	Forest	
Invaded vegetation type	Roadside maintenance	4,400 sq. ft.
Gross Area	Other man-made disturbance	
Disturbances & impacts	Douglas Fir, Sugar Pine, Manzanita, Rose Clover, Blue Wild-rye.	
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)		Full west facing exposure, sunny and open.
Weed Information		Weed Identification
Weed genus and species	<i>Melilotus officinalis</i>	<i>Bromus diandrus</i>
Weed common name(s)	Sweet Clover	Ripgut brome
Presence		Presence
Presence or Absence	Yes	Not - LALA4, HYPE, CIVU, RUAR9
Treated		4,400 sq. ft.
Infested area	1-5%	5-25%
Canopy Cover	New growth	Seedling
Appearance	Linear	Scattered patchy
Distribution pattern		Scattered even
Photo documentation	637, 638, 639	
Weed Location		
Geographic location (ID)	L01-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	Along road primarily on downslope side below transmission lines. 2011 Update: Good control of some weeds. No CIVU, RUAR9, HYPE, or LALA4 observed.
Location description		

General Information		ID: L01-10
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011
Observer name(s)		
Site Information		
Site or facility name	El Dorado Powerhouse	
Site address or other description	Powerhouse Road	
Ownership		
Land use type		
Invaded vegetation type	Transportation Corridor	
Gross Area	Forest	2,500 sq. ft.
Disturbances & impacts	Roadside maintenance	
Associated species	Douglas Fir, Big-leaf Maple, Pacific Dogwood, California Hazelhut.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Shady, N-facing slope, gravel road	
Weed Information		
Weed Identification		
Weed genus and species	<i>Rubus discolor</i>	<i>Hypericum perforatum</i>
Weed common name(s)	Himalayan Blackberry	Klamath weed
Presence		
Presence or Absence	Present (not all species)	No CIWU or HYPE
Treated	Yes	2,500 sq. ft. (including downslope and upslope)
Infested area		
Canopy Cover	5-25%	
Appearance	Germg./early growth	Dead
Distribution pattern	Clumpy	
Photo documentation	626, 627	
Weed Location		
Geographic location (ID)	L01-10 (previously 05-08)	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	5-15m	
Location description	Near rock/fence retaining wall; downslope side also has a small linear stretch of RUAR9 up the road from retaining wall(50'). Changed to a line feature for this occurrence (prev 05-08). 2011 Update: Coming back, moderate control on roadside.	

General Information				ID: L01-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	Logan McCarthy	6/22/2011	New Line
Observer name(s)				
Site or facility name	EID Penstock	Between forebay reservoir and tunnel		
Site address or other description				
Ownership				
Land use type	Transportation Corridor			
Invaded vegetation type	Forest	1000 sq. ft.		
Gross Area	Roadside maintenance	Other man-made disturbance		
Disturbances & impacts	Black Oak, Manseneda, Mountian Misery.			
Associated species				
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Full sun plus gravel soil.			
Weed Information				
Weed genus and species	Centaurea solstitialis	<i>Lathyrus latifolius</i>	<i>Bromus diandrus</i>	Weed Identification
Weed common name(s)	Star Thistle	Sweet Pea	Ripgut	
Presence				
Presence or Absence	Present (all)			
Treated	No	500 sq. ft.	(including down slope and up slope)	
Infested area		<1%	1-5%	1-5%
Canopy Cover		Germ'g./early growth	New growth	Flowering
Appearance				
Distribution pattern	Scattered even			
Photo documentation	653			
Weed Location				
Geographic location (ID)	Line 01	6/22/11		
Coordinate system	Ca. State Plane Zone 2			
Datum	NAD83			
Location data accuracy	5-15m			
Location description	In turn out East of big dip/ravine.			

General Information		ID: L02-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Powerhouse Road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	5000 sq. ft.	
Disturbances & impacts	Roadside maintenance	Other man-made disturbance
Associated species	Douglas Fir, Canyon Live Oak, Black Oak, Big-leaf Maple, California Hazelnut, Poison Oak.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Northeast exposure - full sun	
Weed Information		Weed Identification
Weed genus and species	<i>Rubus armeniacus</i>	<i>Hypericum perforatum</i>
Weed common name(s)	Himalayan Blackberry	Klamath Weed
Presence or Absence		Presence
Treated	Growing Back	No - HYPE
Infested area	5,000 sq. ft.	
Canopy Cover	<1%	0%
Appearance	Germ'g./early growth	Dead
Distribution pattern	Linear	Clumpy
Photo documentation	635, 636	
Weed Location		
Geographic location (ID)	L02-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Below power lines. 2011 Update: Good control greatly reduced RUAR9.	

General Information			ID: L02-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	Logan McCarthy	6/22/2011
Observer name(s)			
Site or facility name	EID Penstock		Site Information
Site address or other description	Between forebay reservoir and tunnel		
Ownership			
Land use type	Water Transport Facility		
Invaded vegetation type	Forest		
Gross Area	2000 sq. ft.		
Disturbances & impacts	Roadside maintenance	Trail Maintenance	
Associated species	Cedar, Ponderosa Pine, White Pine, Mountain Miser.		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Partly Shaded		
Weed Information			Weed Identification
Weed genus and species	<i>Leucanthemum vulgare</i>	<i>Hypericum perforatum</i>	
Weed common name(s)	Ox Eye	Klamath Weed	
Presence or Absence	Present (all)		Presence
Treated	No		
Infested area	250 sq. ft.		
Canopy Cover	<1%		
Appearance	New growth		
Distribution pattern	Linear		
Photo documentation	656		
Weed Location			
Geographic location (ID)			
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	1-5m		
Location description	Penstock access road, west of Kodiak trail; weeds continue downslope along an old skid road.		

General Information			ID: L03-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	5/21/2010	
Observer name(s)			
Site or facility name	ELD Penstock		Site Information
Site address or other description	Between forebay reservoir and tunnel		
Ownership			
Land use type	Water Transport Facility		
Invaded vegetation type	Forest		
Gross Area	0.1 acres		
Disturbances & impacts	Pipe Maintenance		
Associated species	Douglas Fir, Ponderosa Pine, Black Oak, Manzanita.		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Exposed, open, 15 - 25% slopes		
Weed Information			
Weed genus and species	Rubus discolor	Lathyrus latifolius	Weed Identification
Weed common name(s)	Himalayan Blackberry	Perennial Sweet Pea	
Presence or Absence	Present (all)	Leucanthemum vulgare	
Treated	Yes	Ox Eye	
Infested area	4,350 sq. ft.	Aegilops triuncialis	
Canopy Cover	<1%	Hypericum perforatum	
Appearance	New growth	Barbed goat grass	
Distribution pattern	Scattered patchy	Klamath Weed	
Photo documentation	654, 655		
Weed Location			
Geographic location (ID)	L03-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	< 1m		
Location description	Edge of Penstock road on downslope, south side of road; continues into a ravine (most weeds in ravine). 2011 Update RUAR9 present and returning, few AETR on up-hill slope (west side).		

General Information			ID: L03-09
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011	
Observer name(s)			
Site or facility name	EID Penstock	Between Forebay reservoir and Tunnel.	Site Information
Ownership			
Land use type	Water Transport Facility		
Invaded vegetation type	Forest		
Gross Area	1500 sq. ft.		
Disturbances & impacts	Roadside maintenance		
Associated species	Douglas Fir, Ponderosa Pine, Mountain misery.		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	open, exposed, gentle slope		
Weed Information			Weed Identification
Weed genus and species	<i>Rubus discolor</i>	<i>Lathyrus latifolius</i>	<i>Leucanthemum vulgare</i>
Weed common name(s)	Himalayan Blackberry	Perennial Sweet Pea	Ox Eye Daisy
Presence or Absence	Present (all)	Presence	
Treated	Yes		
Infested area	1500 sq. ft.		
Canopy Cover	5-25%	5-25%	
Appearance	New growth	New growth	
Distribution pattern	Clumpy	Linear	
Photo documentation	649, 650, 651		
Weed Location			
Geographic location (ID)	L03-09		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	< 1m		
Location description	Just west of L04-08; South side of road.	2011 Update: good control along Penstock, similar to 2010; weeds present outside ROW.	

General Information		ID: L04-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011
Observer name(s)		
Site or facility name	ELD Penstock	
Site address or other description	Between Forebay reservoir and tunnel	
Ownership	Water Transport Facility	
Land use type	Forest	
Invaded vegetation type		
Gross Area	0.5 acres	
Disturbances & impacts	Pipe Maintenance	Other man-made disturbance
Associated species		tree removal
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Ponderosa Pine, Black Oak. Very exposed.	
Weed Information		
Weed genus and species	<i>Cirsium vulgare</i> , Bull Thistle,	<i>Rubus discolor</i> Himalayan Blackberry
Weed common name(s)		<i>Lathyrus latifolius</i> Perennial Sweet Pea
Presence or Absence	Present (all)	<i>Leucanthemum vulgare</i> <i>Bromus diandrus</i> Ox Eye Daisy Ripgut
Treated	Not all	
Infested area	0.5 acres	
Canopy Cover	<1%	25-50%
Appearance	New growth	New growth
Distribution pattern	Scattered even	Linear
Photo documentation	646, 647, 648	
Weed Location		
Geographic location (ID)	L04-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	<1m	Much of the HBB is downslope from the Penstock road in a disturbed area outside the project boundary. 2011 Update: Good control, most weeds on slope below and near Penstock and access road.
Location description		

General Information		ID: L05-08		
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/22/2011		
Observer name(s)				
Site or facility name	EID Penstock	Site Information		
Site address or other description	Between outlet of Forebay Reservoir and Tunnel.			
Ownership	Water Transport Facility			
Land use type	Forest			
Invaded vegetation type	0.1 acres			
Gross Area	Pipe Maintenance			
Disturbances & impacts				
Associated species	Ponderosa Pine, Annual Grasses, other weedy species, incense cedar.			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Open area, fairly level.			
Weed Information				
Weed Identification				
Weed genus and species	<i>Aegilops triuncialis</i>	<i>Lathyrus latifolius</i>		
Weed common name(s)	Barbed goatgrass	Perennial Sweet Pea		
Presence				
Presence or Absence	Not all - No CIVU			
Treated	Yes			
Infested area	0.1 acres			
Canopy Cover	<1%	<1%		
Appearance	New growth	Flowering		
Distribution pattern	Scattered even			
Photo documentation	643, 644, 645			
Weed Location				
Geographic location (ID)	L05-08			
Coordinate system	Ca. State Plane Zone 2			
Datum	NAD83			
Location data accuracy	< 1m			
Location description	Between Penstock and access road to base of forebay. 2011 Update: Photo 645 is of berm between Penstock and access road. Good control of AETR; Scattered other weed species, especially along berm between penstock and dirt road to south.			

## APPENDIX C

### EID Weed Observation and Monitoring Form - Highway Cut Road and Other Canal Access Roads Along Beat 4

<b>Photo Log</b>			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
659/660	L15-08	SW	RUAR9 on shoulder near gate; appears recently sprayed, Highway Cut Road
661	24-08	SW	RUAR9 along shoulder
662/663	L14-08	SW	RUAR9/LALA4 increasing - very dense
664	L14-08	SW	RUAR9 - very lush growth
665	05-10	W	Increasing - RUAR9/CIVU/VETH - growing into road
666/667	22-08	W/NW	RUAR9 along road shoulder – low density
668	21-08	SW	Very active RUAR9 on side of road – 1 <sup>st</sup>
669	21-08	NW	RUAR9 NW side of road – 2 <sup>nd</sup>
670	21-08	NW	Small patch of RUAR9 NW side of road – 3 <sup>rd</sup> patch
671	20-08	NW	RUAR9 coming back after treatment
672	19-08	NW	RUAR9 coming back near stump
673	18-08	SW	RUAR9 coming back
674	L13-08	NE	R-83 access road – RUAR9
675/676	L13-08	NW/SE	Dense RUAR9 along N side of road
677	04-09	N-NW	RUAR9 on E side of road near large P.pine
678	L06-09	E	MEOF at end of road
679	L12-08	NW	Dense RUAR9 - on n shoulder of El Dorado Ditch road
<b>Photo Log</b>			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
680	L12-08	NW	RUAR9 in road

## Notes

---

Page 2

\* Formerly 2 points, 16-08 and 03-09

General Information		ID: 04-09
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/23/2011
Observer name(s)		
Site or facility name	Access Road	Road from Hazel Creek Road to Hazel Tunnel
Ownership		Transportation Corridor
Land use type	Forest	
Invaded vegetation type	Roadside maintenance	500 sq. ft.
Gross Area		
Disturbances & impacts		
Associated species		Douglas Fir, Ponderosa Pine, Incense Cedar, Big-leaf Maple, California Rose.
Environmental Conditions (e.g. soil conditions, exposure, etc.)		Gravel along Road
Weed Information		Weed Identification
Weed genus and species	<i>Rubus discolor</i>	
Weed common name(s)	Himalayan Blackberry	
Presence or Absence	Present (all)	Presence
Treated	No	
Infested area		500 sq. ft.
Canopy Cover	25-50%	
Appearance	New growth	
Distribution pattern	Clumpy	
Photo documentation	677	
Weed Location		
Geographic location (ID)	04-09	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Approx. 150' from gate at start of road near large Ponderosa pine. Minor occurrence. 2011: Occurrence is slowly spreading. Also noted very sparse, scattered HYPE along road.	

General Information		ID: 05-10
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/23/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Highway Cut Road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	250-500 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	Mixed Conifer and Hardwood	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Disturbed area in a turnout along the road	
Weed Information		
Weed genus and species	<i>Rubus discolor</i>	<i>Verbascum thapsus</i>
Weed common name(s)	Himalayan Blackberry	Woolly Mullein
Presence or Absence	Present (all)	<b>Presence</b>
Treated	Unknown	
Infested area	500 sq. ft.	
Canopy Cover	<1%	
Appearance	New growth	
Distribution pattern	Clumpy	
Photo documentation	665	
Weed Location		
Geographic location (ID)	05-10	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Along edge of road between L14-08 and 22-08 - Dense RUAR9. 2011 Update: Growing back vigorously.	

General Information		ID: 18-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/23/2011
Observer name(s)		Site Information
Site or facility name	Access Road	
Site address or other description	Highway Cut Road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	500 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Mixed Conifer and Hardwood; some riparian associates.  Shady, slight slope to NW	
Weed Information		Weed Identification
Weed genus and species	<i>Rubus discolor</i>	
Weed common name(s)	Himalayan Blackberry	Presence
Presence or Absence (If P & A list Absence next to drop list)	Present (all)	
Treated	Growing Back	
Infested area	500 sq. ft.	
Canopy Cover	1-5%	
Appearance	New growth	
Distribution pattern	Clumpy	
Photo documentation	673	Weed Location
Geographic location (ID)	18-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	At sharp hairpin turn where road incline increases, on downhill side of road. 2011 Update: RUAR9 growing back mixed with thimbleberry.	

General Information		ID: 19-08	
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/23/2011	
Observer name(s)			
Site or facility name	Access Road	Site Information	
Site address or other description	Highway Cut Road		
Ownership			
Land use type	Transportation Corridor		
Invaded vegetation type	Forest		
Gross Area	250-500 sq. ft.		
Disturbances & impacts	Roadside maintenance		
Associated species	Mixed Conifer and Hardwood		
Environmental Conditions (e.g. soil conditions, exposure, etc.)			
Weed Information		Weed Identification	
Weed genus and species	<i>Rubus armeniacus</i>		
Weed common name(s)	Himalayan Blackberry		
		Presence	
Presence or Absence	Present (all)		
Treated	Growing Back		
Infested area	250 sq. ft.		
Canopy Cover	5-25%		
Appearance	New growth		
Distribution pattern	Clumpy		
Photo documentation	672		
Weed Location			
Geographic location (ID)	19-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	< 1m		
Location description	Along edge of road. 2010 Update: RUAR9 coming back, esp. near stump. 2011 Update: Still continuing to grow same as 2010.		

General Information		ID: 20-08
Collection date (mm/dd/yyyy)	6/23/2011	
Observer name(s)	Ethan Koenigs	
Site or facility name	Access Road	Site Information
Site address or other description	Highway Cut Road	
Ownership	Transportation Corridor	
Land use type	Forest	
Invaded vegetation type	2,000 sq. ft.	
Gross Area	Roadside maintenance	
Disturbances & impacts		
Associated species	Mixed Conifer and Hardwood	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Shady, moist soil	
Weed Information		Weed Identification
Weed genus and species	<i>Rubus discolor</i>	<i>Lathyrus latifolius</i>
Weed common name(s)	Himalayan Blackberry	Perennial Sweet Pea
Presence		Presence
Present (not all species)	Present	Perennial Sweet Pea absent
Treated	Growing Back	
Infested area	2,000 sq. ft.	
Canopy Cover	25-50%	
Appearance	New growth	
Distribution pattern	Linear	
Photo documentation	671	
Weed Location		
Geographic location (ID)	20-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	<1m	
Location description	At a wide shallow bend in the road. 2010 Update: Good control; no LALA4 ; RUAR9 controlled along shoulder in 2009 but coming back. 2011 Update: Vigorously returning. No apparent treatement this year	

General Information		ID: 21-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/23/2011
Observer name(s)		
Site Information		
Site or facility name	Access Road	
Site address or other description	Highway Cut Road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	1,250 sq. ft.	
Disturbances & impacts	Roadside maintenance	Other man-made disturbance
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Mixed Conifer and Hardwood shady, gentle slope	
Weed Information		
Weed Identification		
Weed genus and species	<i>Cirsium vulgare</i>	<i>Rubus discolor</i>
Weed common name(s)	Bull Thistle	Himalayan Blackberry
Presence		
Presence or Absence	Present (not all species)	No CIVU
Treated	Unknown	
Infested area	1,250 sq. ft.	
Canopy Cover	5-25%	
Appearance	New growth	
Distribution pattern	Scattered patchy	Clumpy
Photo documentation	668, 669, 670	
Weed Location		
Geographic location (ID)	21-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1-5m	
Location description	At a landing and a broad curve; 3 sep. patches; 1st patch at the landing near slash pile; 2nd +100'; 3rd + 100'. 2011 Update: 1st patch 500sq. ft. growing back and larger, mostly on SE side of pile. No BT at 1st. 3rd patch 600sq. ft. growing vigorously since last year.	

General Information		ID: 22-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/23/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Highway Cut Road	
Ownership	Transportation Corridor	
Land use type	Forest	
Invaded vegetation type	1250 sq. ft.	
Gross Area	Roadside maintenance	
Disturbances & impacts		
Associated species	Mixed Conifer and Hardwood	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	near small drainage, mostly shaded	
Weed Information		
Weed Identification		
Weed genus and species	<i>Rubus discolor</i>	
Weed common name(s)	Himalayan Blackberry	
Presence		
Presence or Absence	Present (all)	
Treated	Growing Back	
Infested area	1250 sq. ft.	
Canopy Cover	5-25%	
Appearance	New growth	
Distribution pattern	Scattered patchy	
Photo documentation	666, 667	
Weed Location		
Geographic location (ID)	22-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	5-15m	
Location description	2 patches about 300' apart; 1st patch is RUARG at a deep and wide bend in the road on S Side; 2nd is 300' up (west). 2011 Update: First patch continues to grow into road. Second patch is small scattered patches on both sides of the road. 1st patch 5-25%, 2nd -1-5%	

General Information		ID: 24-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/23/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Highway Cut Road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	500 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	Mixed Conifer and Hardwood	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Northwest exposure; gentle slope	
Weed Information		
Weed genus and species	<i>Rubus discolor</i>	
Weed common name(s)	Himalayan Blackberry	
Presence or Absence	Present (all)	
Treated	Growing Back	
Infested area	250 sq. ft.	
Canopy Cover	5-25%	
Appearance	New growth	
Distribution pattern	Clumpy	
Photo documentation	661	
Weed Location		
Geographic location (ID)	24-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	5-15m	
Location description	1/8 to 1/4 mile from intersection with Hazel Valley Road. 2011 Update: Continuing to grow back.	

General Information		ID: L03-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/23/2011
Observer name(s)		
Site or facility name	Access Road	Site Information
Ownership	El Dorado Ditch Rd.	
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	800 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	Douglas Fir, Ponderosa Pine, Dogwood, Big-leaf Maple, Thimble Berry, Native blackberry.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Shady near drainage.	
Weed Information		Weed Identification
Weed genus and species	<i>Rubus discolor</i>	
Weed common name(s)	Himalayan Blackberry	
Presence or Absence	Present (all)	Presence
Treated	No	
Infested area	800 sq. ft.	
Canopy Cover	5-25%	
Appearance	Germ g./early growth	
Distribution pattern	Clumpy	Linear
Photo documentation	683-685	
Weed Location		
Geographic location (ID)	L03-11 (formerly points 16-08, 03-09)	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Combined points due to proximity and patchy RUAR9 between them; 2011 Update: Increasing presence of RUAR9	

General Information		ID: L06-09
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/23/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Hazel Creek Tunnel Road	
Ownership		
Land use type	Transportation Corridor	Water Transport Facility
Invaded vegetation type	Forest	
Gross Area	2600 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	Douglas Fir, Ponderosa Pine, Incense Cedar, Cinquefoil, Deer Brush, Annual Grasses.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Exposed; very rocky, volcanic soil	
Weed Information		Weed Identification
Weed genus and species	<i>Melilotus officinalis</i>	
Weed common name(s)	White Sweet Clover	
Presence or Absence	Present (all)	Presence
Treated	No	
Infested area	1000 sq. ft.	
Canopy Cover	5-25%	
Appearance	New growth	
Distribution pattern	Clumpy	Scattered patchy
Photo documentation	678	Linear
Weed Location		
Geographic location (ID)	L06-09	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	5-15m	
Location description	At the terminus of Hazel tunnel road ('last 150'). 2011 Update: Appears same as in years past, patchy & clumpy MEOF.	

General Information		ID: L12-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/23/2011
Observer name(s)		Site Information
Site or facility name	Access Road	
Ownership	El Dorado Ditch	
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	15,000 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	Douglas Fir, Ponderosa Pine, Dogwood, Big-leaf Maple, Thimble Berry, native blackberry.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Mostly NW - NE exposer	Weed Information
Weed Identification		
Weed genus and species	<i>Cirsium vulgare</i>	<i>Rubus armeniacus</i>
Weed common name(s)	Bull Thistle	Himalayan Blackberry
		Klamath Weed
Presence		
Presence or Absence	Present (all)	
Treated	No	
Infested area	15,000 sq. ft.	
Canopy Cover	<1%	75-95% <1%
Appearance	New growth	New growth
Distribution pattern	Clumpy	Linear
Photo documentation	679-681	
Weed Location		
Geographic location (ID)	L12-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	Begins near intersection with Hazel Tunnel Road spur and extends down to next spur road to North. 2011 Update: RUAR9 very dense; mostly on S. side of road but also on N. side, less dense.
Location description		

General Information			ID: L13-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/23/2011	
Observer name(s)			
Site or facility name	Access Road		
Site address or other description	Spillway 33/ Rd. 83		
Ownership			
Land use type	Water Transport Facility	Transportation Corridor	
Invaded vegetation type	Forest	1,000 sq. ft.	
Gross Area	Roadside maintenance	Douglas Fir, Ponderosa Pine, Incense Cedar, Thimbleberry, Annual Grasses.	
Disturbances & impacts			
Associated species			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	north slope, shady		
Weed Information			
Weed genus and species	<i>Cirsium vulgare</i>	<i>Rubus armeniacus</i>	<i>Verbasium thapsus</i>
Weed common name(s)	Bull Thistle	Himalayan Blackberry	Wooly Mullein
Weed Identification			
Presence or Absence	Present (not all species)	No VETH	
Treated	No	500 sq. ft.	
Infested area	<1%	25-50%	
Canopy Cover	Germ'g/early growth	New growth	
Appearance	Clumpy	Linear	
Distribution pattern			
Photo documentation	674-676		
Weed Location			
Geographic location (ID)	L13-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	5-15m		
Location description	Along road on downslope side. 2011 Update: RUAR9 increasing		

General Information		ID: L14-08
Collection date (mm/dd/yyyy)	6/23/2011	
Observer name(s)	Ethan Koenigs	
Site or facility name	Access Road	Site Information
Site address or other description	Highway Cut Road	
Ownership	Transportation Corridor	
Land use type	Forest	
Invaded vegetation type	4500 sq. ft.	
Gross Area	Roadside maintenance	
Disturbances & impacts		
Associated species	Mixed Conifer and Hardwood	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	near a drainage,	Weed Information
Weed Information		Weed Identification
Weed genus and species	<i>Cirsium vulgare</i>	<i>Rubus discolor</i>
Weed common name(s)	Bull Thistle	Himalayan Blackberry
Presence or Absence	Present (all)	Presence
Treated	Growing Back	
Infested area	4,500 sq. ft.	
Canopy Cover	<1%	25-50%
Appearance	New growth	New growth
Distribution pattern	Clumpy	Scattered even
Photo documentation	662, 663, 664	
Geographic location (ID)	L14-08	Weed Location
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	Between 2 small drainages, main creek is just downslope (North). 2011 Update: Occurrence Rapidly increasing in size, fairly continuous between drainages.
Location description		

General Information		ID: L15-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/23/2011
Observer name(s)		
Site or facility name	Access Road	<b>Site Information</b>
Site address or other description	Highway Cut Road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	3000 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	Douglas Fir, White Fir, Incense Cedar, Ponderosa Pine, Dogwood, Black Oak, Deer Brush	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	NW facing slope, gentle slope, shady	
Weed Information		
Weed genus and species		Weed Identification
Weed common name(s)		
	<i>Rubus armeniacus</i>	<i>Cirsium vulgare</i>
	Himalayan Blackberry	Bull Thistle
		Lathyrus latifolius
		Perennial Sweet Pea
Presence		
Present or Absence	Present (not all species)	No CIVU or LALA4
Treated	Unknown	
Infested area	3000 sq. ft.	
Canopy Cover	5-25%	
Appearance	New growth	Dead
Distribution pattern	Scattered even	Linear
Photo documentation	659, 660	
Weed Location		
Geographic location (ID)	L15-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	Along both shoulders from intersection w/ Hazel Valley Rd. 9, RUAR9 growing bac; 2011 Update: RUAR9 Same as 2010 but no other weed species observed.
Location description		

**APPENDIX C**

**EID Weed Observation and Monitoring Form**

**Canal Beats 4 & 5**

<b>Photo Log</b>			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
686, 687	04-10	SE	Bridge over canal, weed patch –MEOF, CIVU – in grassy area
689	17-08	SW	LALA4 eradicated at Hazel Creek Tunnel
690, 691	L09-08	S	LALA4 at Camp 5 (Building)
692	L08-08	SE	Large clump of CIVU; others
693	L08-08	NW	Access road w/ multiple weeds CIVU, HIN3, MEOF
694	L08-08	NW	Clump of VETH; HIN3 scattered
695	L08-08	SE	Dense MEOF on shoulder to south/ SW side of road
696	01-11	NE down	Large clump of LALA4
697	L07-08	E	Decent control of CIVU
698	L04-11	E	New flume; scattered MEOF and LALA4; mostly grasses
699	03-10	E/NE	AETR, MEOF, BRTE near bridge
700	02-10	N/NE	Sparse BRTE, VETH
701	01-10	W/NW	Few small VETH
702/703	45-08	NE/SW	LALA4 eradicated

**Notes:**

---



---



---



---



---



---



---



---



---



---

General Information		ID:01-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/29/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Beat 5	
Ownership	EID	
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	300 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)		Weed Information
Weed genus and species		Weed Identification
Weed common name(s)		
Presence or Absence	Present (all)	
Treated	No	
Infested area	100 sq. ft.	
Canopy Cover	<1%	
Distribution pattern	Flowering	
Photo documentation	Clumpy	
	696	Weed Location
Geographic location (ID)	01-11	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1-5m	Near auto spillway; one small patch of <i>LALA4</i> on east side of spill; few CIVU and LALA4 on west side of spillway.
Location description		

General Information		ID: 01-10
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/29/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Beat 5	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	100 sq. ft.	
Disturbances & impacts	Canal Maintenance	Other man-made disturbance
Associated species	White fir, Douglas Fir, black oak, Dogwood, Incense Cedar, other weedy species.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Exposed opening in tree cover/ NE-facing slope.	
Weed Information		Weed Identification
Weed genus and species	<i>Verbascum thapsus</i>	
Weed common name(s)	woolly mullein	
Presence or Absence	Present (all)	Presence
Treated	Yes	
Infested area	100 sq. ft.	
Canopy Cover	1-5%	
Distribution pattern	New growth	
Photo documentation	Clumpy	
	701	Weed Location
Geographic location (ID)	01-10	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1-5m	
Location description	N. side of canal, downslope - very minor occurrence. 2011 Update: 11 plants.	

General Information			ID: 02-10
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/29/2011	
Observer name(s)			
Site or facility name	El Dorado Canal		Site Information
Site address or other description	Beat 5		
Ownership			
Land use type	Water Transport Facility		
Invaded vegetation type	Forest	1000 sq. ft.	
Gross Area	Canal Maintenance		
Disturbances & impacts			
Associated species	black oak, canyon live oak, buckbrush, white leaf manzanita, Sierra coffeeberry, mixed grasses		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Exposed, rocky area, volcanic soil		
Weed Information			Weed Identification
Weed genus and species	<i>Bromus tectorum</i>	<i>Verbascum thapsus</i>	
Weed common name(s)	cheat grass	woolly mullein	
Presence or Absence	Present (all)		Presence
Treated	No	1000 sq. ft.	
Infested area	<1%	<1%	
Canopy Cover	Seeding		
Distribution pattern	Scattered even	Linear	
Photo documentation	700		
Weed Location			
Geographic location (ID)	02-10		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	5-15m	No GPS	
Location description	NW side of canal, near alarm 23. 2011 Update: Recently worked on canal berm. Light cover on downslope side of berm. Few VETH plants.		

General Information		ID: 03-10
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/23/2011
Observer name(s)		Site Information
Site or facility name	El Dorado Canal	
Site address or other description	Beat 5	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	1000 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species	Ponderosa pine, white fir, incense cedar, big-leaf maple, willow	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Exposed, disturbed area	Weed Information
Weed Identification		
Weed genus and species	<i>Bromus tectorum</i>	<i>meliolotus officinalis</i>
Weed common name(s)	cheat grass	sweet clover
		Aegilops triuncialis
		Barbed goat grass
Presence		
Presence or Absence	Present (all)	
Treated	No	
Infested area	1000 sq. ft.	
Canopy Cover	<1%	<1%
Distribution pattern	Seeding	New growth
Photo documentation	Scattered even	Linear
		Clumpy
		699
Weed Location		
Geographic location (ID)	03-10	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1-5m	S. side of canal in a clearing at the end of a gravel road near a wood bridge across the canal. 2011 Update: New AETR patch.
Location description	All weeds sparse.	

General Information		ID: 04-10
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/29/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Beat 4	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	3000 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species	white fir, ponderosa pine, douglas fir, incense cedar, big leaf maple, thimbleberry, <i>Juncus</i> sp., <i>Elymus glaucus</i>	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	NE - facing slope, a little wet (potential wetland seep) - use Caution when treating.	
Weed Information		Weed Identification
Weed genus and species	<i>Hypericum perforatum</i>	<i>Cirsium vulgare</i>
Weed common name(s)	Klamath weed	bull thistle,
		sweet clover
Presence or Absence	Present (all)	Presence
Treated	No	
Infested area	300 sq. ft.	
Canopy Cover	1-5%	1-5%
Distribution pattern	New growth	New growth
Photo documentation	Scattered patchy	Scattered patchy
	686, 687	
Weed Location		
Geographic location (ID)	04-10	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	5-15m	No GPS
Location description	S. side of canal, near end of rd. 83, near bridge. 2011 Update: Similar to last year; more grass this year; very little weed spread.	

General Information		ID: 17-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/29/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Beat 4	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	250 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species	Ponderosa Pine, Douglas Fir, Black Oak, Mountain Miser, Deer Brush	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Northwest facing slope	
Weed Information		Weed Identification
Weed genus and species	<i>Leucanthemum vulgare</i>	<i>Lathyrus latifolius</i>
Weed common name(s)	Ox-eye Daisy	Perennial Sweet Pea present
Presence		
Presence or Absence	Absent	
Treated	Yes	sq. ft.
Infested area		
Canopy Cover		
Distribution pattern		
Photo documentation	689	Weed Location
Geographic location (ID)	17-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Along canal near Hazel Crk tunnel. 2011 Update: LALA4 and LEVU remain eradicated.	

General Information		ID: 45-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/29/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Ownership	Beat 5	
EID		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	1000 sq. ft.	
Disturbances & impacts	Canal Maintenance	Roadside maintenance
Associated species	Ponderosa Pine, Douglas Fir, White Fir, other weedy species.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Moderately shaded, N-facing slope	
Weed Information		Weed Identification
Weed genus and species	<i>Lathyrus latifolius</i>	
Weed common name(s)	Perennial Sweet Pea	
Presence		
Presence or Absence	Present (all)	
Treated	Most but not all	
Infested area	0 sq. ft.	
Canopy Cover	<1%	
Distribution pattern	New growth	
Photo documentation	122	West Location
Geographic location (ID)	45-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	West end of Beat 5 near access gate and tunnel to Forebay on north bank. 2011 Update: Treated and controlled very well; appears eradicated.
Location description		

General Information		ID: L04-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/29/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Ownership	Beat 5	
EID		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	5500 sq. ft.	
Disturbances & impacts	Maintenance	
Associated species	Incense cedar, ponderosa pine, big leaf maple, grasses	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Recently repaired flume and ground disturbance; strawed; N. facing slope	
Weed Information		Weed Identification
Weed genus and species	<i>Lathyrus latifolia</i>	<i>Melilotus officinalis</i>
Weed common name(s)	Perennial Sweet Pea	sweet clover
Presence		Presence
Presence or Absence	Present (all)	
Treated	No	
Infested area	5500 sq. ft.	
Canopy Cover	<1%	<1%
Distribution pattern	New growth	New growth
Photo documentation	Scattered patchy	Linear
	698	
Weed Location		
Geographic location (ID)	L04-11	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1-5m	Recently repaired flume; northeast side. Scattered low density weeds.
Location description		

General Information		ID: L07-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/29/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Beat 5	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	2000 sq. ft.	
Disturbances & impacts	Canal Maintenance	Roadside maintenance
Associated species	Ponderosa pine, Douglas Fir, black oak, Dogwood, Incense Cedar, other weedy species.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Gravel road/ NE-facing slope	Weed Information
		Weed Identification
Weed genus and species	<i>Cirsium vulgare</i>	<i>Melilotus officinalis</i>
Weed common name(s)	bull thistle	sweet clover
Presence or Absence	Present (not all species)	Presence
Treated	No	sweet clover (absent)
Infested area		2000 sq. ft.
Canopy Cover	<1%	
Distribution pattern	New growth	
Photo documentation	Scattered patchy	Linear
	697	
Geographic location (ID)	L07-08	Weed Location
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1-5m	Along gravel rd. near canal. 2011 Update: Good control; needs additional treatment; few BT observed.
Location description		

General Information		ID: L08-08	
Collection date (mm/dd/yyyy)	Ethan Koenigs	6/29/2011	
Observer name(s)		Site Information	
Site or facility name	El Dorado Canal		
Site address or other description	Beat 5		
Ownership			
Land use type	Water Transport Facility		
Invaded vegetation type	Forest		
Gross Area	0.3 acres		
Disturbances & impacts	Roadside maintenance		
Associated species			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Incense Cedar, White Fir, Douglas Fir, Big-leaf Maple, mountain alder, thimbleberry, Other weeds		
Gravel/Graded area		Weed Information	
Weed genus and species	<i>Verbascum thapsus</i>	<i>Cirsium vulgare</i>	<i>Hirschfeldia incana</i>
Weed common name(s)	Woolly Mullein	Bull Thistle	Yellow Sweet Clover
Presence or Absence	Present (all)	Presence	Shortpod Mustard
Treated	No		
Infested area	5000-7000 sq. ft.		
Canopy Cover	1-5%	1-5%	1-5%
Appearance	New growth	New growth	Flowering
Distribution pattern	Scattered patchy	Scattered patchy	Scattered even
Photo documentation	(NW) 692-695		
Geographic location (ID)		Weed Location	
Coordinate system	L08-08		
Datum	Ca. State Plane Zone 2		
Location data accuracy	NAD83		
Location description	<1m	Near camp 5; along road between canal and road on downslope bank. 2011 Update: Extend the line from canal to gate. Significant increase in most weeds along entire road, especially CIVU. HIN3 new this year. Scattered VETH and LALA4; MEOF and CIVU on north side of canal along drainage.	

General Information		ID: L09-08
Collection date (mm/dd/yyyy)	6/29/2011	
Observer name(s)	Ethan Koenigs	
Site or facility name	El Dorado Canal	Site Information
Ownership	Beat 5	
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	1000 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species	Ponderosa Pine, Douglas Fir, Black Oak, Big-leaf Maple, Deer Brush	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	northwest exposure, partly shaded	
Weed Information		Weed Identification
Weed genus and species	<i>Lathyrus latifolius</i>	
Weed common name(s)	Perennial Sweet Pea	
Presence or Absence	Present (all)	Presence
Treated	No	
Infested area	1000 sq. ft.	
Canopy Cover	50-75%	
Appearance	New growth	
Distribution pattern	Clumpy	
Photo documentation	690, 691	
Weed Location		
Geographic location (ID)	L09-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	Just below Camp 5. 2011 Update: North bank bench clear. Mostly concentrated around shed structure, extending east along south bank to bridge; may require targeted treatment using physical removal and sprays.
Location description		

**APPENDIX C****EID Weed Observation and Monitoring Form**

Canal Beat 3, Access roads: Camp P, Rockcrusher, Camp X, Camp 2

<b>Photo Log</b>			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
704	08-09	S	turnout on W side of road; patch of RUAR9, few CIVU
705, 706	L25-08	S	CIVU on E side of road
707	07-09	SE	BRTE
708, 709	L07-09	S	BRTE and BRDID2 along road
710	L22-08	W/SW	MEOF on side of Rock Crusher road; sprayed
711	34-08	NE	HYPE controlled/treated – some still present
712	33-08	SE	Patchy LALA4 – Canal Beat 3
713	33-08	SE	LALA4, scattered TOAR – Canal Beat 3
714, 715	L24-08	NE	Sparse, scattered TOAR – Camp P Road
716	32-08	SW/NE	CIVU sprayed – Camp P Road
717	L23-08	E	Good control of TOAR – Camp P Road
718	31-08	E	Sparse TOAR – very minor – Camp P Road
719, 720	30-08	E	TOAR – mixed with other vegetation (native berry) – Camp P Road/ CIVU sprayed

Photo Log			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
721	L20-08	SE	Good control of weeds along road
722	L20-08	N	Dense RUAR9 on SPI land
723	L17-08	W	Treated area at top of road near gate; spotty BRTE
724	L17-08	W	Treated spur road; RUAR9 and LALA4 dying on road, but growing on margins
725	L17-08	NW/SE	Recently sprayed LALA4
726	L17-08	NW	Heavy LALA4 at bottom of road
727, 728	29-08	SE/NW	Treated area - good control/ dying weeds
729, 730	L21-08	SE/NW	Treated weeds; MEOF; Good control along road
Notes			
Page 2			

General Information		ID: 07-09
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/1/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Camp 2 Road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	150 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Canyon Live Oak, Doug Fir, Incense Cedar, Deer Brush West-facing slope, rocky soil.	
Weed Information		Weed Identification
Weed genus and species	<i>Bromus tectorum</i>	
Weed common name(s)	Cheat grass	
Presence or Absence	Present (all)	
Treated	No	
Infested area	150 sq. ft.	
Canopy Cover	5-25%	
Appearance	Seedling	
Distribution pattern	Linear	
Photo documentation	Scattered even 707	
Weed Location		
Geographic location (ID)	07-09	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Approximately 250 ft. from second gate, on west side of the road. 2011 Update: Appears same as 2010.	

General Information		ID: 08-09
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/1/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Camp 2 Road	
Ownership	Transportation Corridor	
Land use type	Forest	
Invaded vegetation type	Roadside maintenance	1000 sq. ft. clearing next to road
Gross Area	Douglas Fir, Incense Cedar, Dogwood, various weedy species.	
Disturbances & impacts		
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Disturbed area	
Weed Information		Weed Identification
Weed genus and species	<i>Cirsium vulgare</i>	<i>Rubus armeniacus</i>
Weed common name(s)	Bull Thistle	Himalayan Blackberry
Presence		Wooly Mullein (absent)
Presence or Absence	Present (not all species)	
Treated	No	
Infested area		500 sq. ft.
Canopy Cover	<1%	
Appearance	New growth	
Distribution pattern	Clumpy	
Photo documentation	704	
Weed Location		
Geographic location (ID)	08-09	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Large clearing on west side of road. 2011 Update: Starting new road work; RUAR9 plant still here; approx 6 CIVU.	

General Information	
Collection date (mm/dd/yyyy)	7/1/2011
Observer name(s)	Ethan Koenigs
Site Information	
Site or facility name	Access Road
Site address or other description	Camp P Road; Near intersection with Camp 3 Road
Ownership	Transportation Corridor
Land use type	Forest
Invaded vegetation type	Roadside maintenance
Gross Area	5000 sq. ft.
Disturbances & impacts	Clearing on road and SPI Plantation
Associated species	Mixed Conifer; Deer Brush, multiple weed sp.
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Mostly Gravel within landing/clearing; full sun; flat
Weed Information	
Weed Identification	
Weed genus and species	<i>Bromus tectorum</i>
Weed common name(s)	Cheat grass
	<i>Leucanthemum vulgare</i>
	Ox-eye Daisy
Presence	
Presence or Absence	Present (not all species)
Treated	Yes
Infested area	2,500 sq. ft.
Canopy Cover	<1%
Appearance	<1%
Distribution pattern	Seedling
Photo documentation	Scattered patchy
	727,728
Weed Location	
Geographic location (ID)	29-08
Coordinate system	Ca. State Plane Zone 2
Datum	NAD83
Location data accuracy	< 1m
Location description	At large clearing just before intersection of Camp P Road and Camp 3 Road. 2011 Update: Good treatment (spray) RL BRDID3; few patches of LAL4; overall good control.

**ID: 29-08**


*Rubus armeniacus*  
Himalyan Blackberry

<1%  
Dead  
Scattered patchy

JAR9 looks to be dying; very little

General Information			ID: 30-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/1/2011	
Observer name(s)			
Site or facility name	Access Road		
Site address or other description	Camp P Road		
Ownership			
Land use type	Transportation Corridor		
Invaded vegetation type	Forest	250 sq. ft.	
Gross Area	Roadside maintenance	Other man-made disturbance	
Disturbances & impacts			
Associated species			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Mixed Conifer; Big-leaf Maple, Dog Wood, California Blackberry.	NW exposure, mostly shade	
Weed Information			Weed Identification
Weed genus and species	<i>Torilis arvensis</i>	<i>Cirsium vulgare</i>	
Weed common name(s)	Hedge Parsley	Bull Thistle	
Presence or Absence	Present (all)		
Treated	Partial		
Infested area	200 sq. ft.		
Canopy Cover	<1%		
Appearance	Flowering		
Distribution pattern	Scattered even		
Photo documentation	719, 720		
Weed Location			
Geographic location (ID)	30-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	< 1m		At a gentle bend in the road; upslope side (primarily) near a stump & slash pile. 2011 Update: More CIVU this year; TOAR is scattered on both sides of road; Partial control of weeds.
Location description			

General Information		ID: 31-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/1/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Camp P road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	120 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Mixed Conifer; Big-leaf Maple, Dog Wood N - NW exposure	
Weed Information		Weed Identification
Weed genus and species	<i>Torilis arvensis</i>	
Weed common name(s)	Hedge Parsley	
Presence or Absence	Present (all)	
Treated	Yes	
Infested area	100 sq. ft.	
Canopy Cover	<1%	
Distribution pattern	Flowering	
Photo documentation	Scattered even	
	Linear	
	718	
Weed Location		
Geographic location (ID)	31-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	On shoulder of road (north side); very minor occurrence. 2011 Update: Very little TOAR remaining; small amount of spread to S. side of road.	

General Information		ID: 32-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/1/2011
Observer name(s)	Site Information	
Site or facility name	Access Road	
Ownership	Camp P Road	
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	750 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	Mixed Conifer, Big-leaf Maple	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	NW exposure; relatively recent disturbance;	
Weed Information		Weed Identification
Weed genus and species	<i>Cirsium vulgare</i>	<i>Torilis arvensis</i>
Weed common name(s)	Bull Thistle	Hedge Parsley
Presence or Absence	Present (all)	Presence
Treated	Not all	
Infested area	750 sq. ft.	
Canopy Cover	<1%	
Distribution pattern	New growth	Flowering
Photo documentation	Scattered patchy	Clumpy
	716	716
Weed Location		
Geographic location (ID)	32-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Down slope in an area that was recently graded, straw still remains from erosion control. 2011 Update: Good control, weeds are wilting.	

General Information		ID: 33-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/1/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Ownership	Beat 3	
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	1,500 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species	Mixed Conifer; Ponderosa Pine, Douglas Fir, Incense Cedar, Canyon Live Oak, mugwort, other weedy species.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)		
Weed Information		Weed Identification
Weed genus and species	<i>Lathyrus latifolius</i>	<i>Rubus armeniacus</i>
Weed common name(s)	Perennial Sweet Pea	Himalayan Blackberry
		Hedge Parsley
Presence or Absence	Present (not all species)	RUAR9 (absent)
Treated	Yes	
Infested area	500 sq. ft.	<1%
Canopy Cover	New growth	Dead
Distribution pattern	Scattered patchy	Flowering
Photo documentation	712,713	
Weed Location		
Geographic location (ID)	33-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	South bank of the canal; near access road terminus. 2011 Update: LALA4 on uphill side slope; few patches of LALA4 scattered; TOAR very sparse; mostly controlled next to canal.
Location description		

General Information		ID: 34-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/1/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Rock Crusher Road	
Ownership	Transportation Corridor	
Land use type	Forest	
Invaded vegetation type	Roadside maintenance	
Gross Area	250 sq. ft.	
Disturbances & impacts		
Associated species	Mixed Conifer; cinquefoil, tarweed	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Gently sloping, north-facing exposure in a clearing.	
Weed Information		Weed Identification
Weed genus and species	<i>Hypericum perforatum</i>	<i>Cirsium vulgare</i>
Weed common name(s)	Klamath Weed	Bull Thistle
Presence or Absence	Present (not all species)	Presence
Treated	Yes	Bull Thistle (absent)
Infested area		25 sq. ft.
Canopy Cover	1-5%	
Appearance	Dead	New growth
Distribution pattern	Clumpy	
Photo documentation	711	
Weed Location		
Geographic location (ID)	34-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Small clearing on southeast side of road. 2011 Update: Recently sprayed; looks to be mostly controlled.	

General Information		ID: L07-09	
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/1/2011	
Observer name(s)			
Site or facility name	Access Road	Site Information	
Site address or other description	Camp 2 Road		
Ownership			
Land use type	Transportation Corridor		
Invaded vegetation type	Forest		
Gross Area	0.4 acres		
Disturbances & impacts	Roadside maintenance		
Associated species			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Canyon Live Oak, Manzanita, Douglas Fir; various other grasses and forbes. West-facing slope; very exposed, rocky soil.		
Weed Information		Weed Identification	
Weed genus and species	<i>Bromus tectorum</i>	<i>Bromus diandrus</i>	
Weed common name(s)	Cheat grass	Ripgut Brome	
Presence or Absence	Present (all)	Presence	
Treated	No		
Infested area	0.4 acres		
Canopy Cover	5-25%	5-25%	
Appearance	Senesc.	Seedling	
Distribution pattern	Scattered patchy	Scattered patchy	
Photo documentation	708, 709	Linear	
Weed Location			
Geographic location (ID)	L07-09		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	< 1m		
Location description	Beginning past second gate, near rock outcrops & extending to 250' before tender's house; along road shoulders. Variable weed density. 2011 Update: Same as 2010 but more BRTE than BRDID2.		

General Information		ID: L17-08		
Collection date (mm/dd/yyyy)	Ethan Koeniges	7/1/2011		
Observer name(s)				
Site or facility name	Access Road	Site Information		
Site address or other description	Camp 3 Road			
Ownership				
Land use type	Water Transport Facility			
Invaded vegetation type	Forest			
Gross Area	14,000-15,000 sq. ft.			
Disturbances & impacts	Roadside maintenance Turnouts			
Associated species	Mixed Conifer & Hardwood - many weedy species on shoulder.			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Road terminates near Ogilby Creek. W-facing slope - shaded to open.			
Weed Information				
Weed genus and species	Bromus tectorum	Torilis arvensis	Hypericum perforatum	Lathyrus latifolius
	Cheat grass	Bull Thistle	Hedge Parsley	Perennial Sweet Pea
Presence or Absence	Present (not all species)	Bull Thistle & Klamath weed absent		
Treated	Yes			
Infested area	14,000-15,000 sq. ft.	<1%	<1%	5-25%
Canopy Cover				New growth
Distribution pattern	Seeding			
Photo documentation	Clumpy	Flowering	Clumpy	Scattered patchy
	723, 724, 725, 726			
Weed Location				
Geographic location (ID)	L17-08			
Coordinate system	Ca. State Plane Zone 2			
Datum	NAD83			
Location data accuracy	<1m	From gate on Camp P to canal. 2011 Update: Good control on spur road to NW, heavy LALA4 and RUJAR9 just outside sprayed area; lower road w/significant LALA4; BRTE only near top of road; TOAR spreading on edge of road (upper portion).		
Location description				

General Information			ID: L20-08
Collection date (mm/dd/yyyy)	Ethan Koenigs,		7/1/2011
Observer name(s)			
Site or facility name	Access Road	Site Information	
Site address or other description	Camp P Road - At gate near intersection w/ Camp 3 Road		
Ownership			
Land use type	Water Transport Facility		
Invaded vegetation type	Forest		
Gross Area	1500 sq. ft.		
Disturbances & impacts	Roadside maintenance	SPI plantation to northeast	
Associated species	Mixed Conifer; Deer Brush, Sulfer Pea		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	NW exposure, open; gravelly soil		
Weed Information			
Weed genus and species	<i>Bromus tectorum</i>	<i>Torilis arvensis</i>	Weed Identification
Weed common name(s)	Cheat grass	Hedge Parsley	
Presence or Absence	Present (all)	Presence	
Treated	Yes		
Infested area	1500 sq. ft.		
Canopy Cover	<1%	<1%	
Appearance	Dead	Dead	
Distribution pattern	Clumpy	Linear	
Photo documentation	721,722		
Weed Location			
Geographic location (ID)	L20-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	< 1m		
Location description	Beginning at gate and extending down road for about 250ft. 2011 Update: Good control of RUAR9; large, dense patch of RUAR9 on adjacent SPI land		

General Information		ID: L21-08
Collection date (mm/dd/yyyy)	Ethan Koenigs,	7/1/2011
Observer name(s)		
Site Information		
Site or facility name	Access Road	
Site address or other description	Camp P road	
Ownership		
Land use type		
Invaded vegetation type		
Gross Area	12,000 sq. ft.	
Disturbances & impacts	Roadside maintenance	SPI Plantation to North-east side of road
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Mixed Conifer; Deer Brush, Maple  Gravel road and shoulder.	
Weed Information		
Weed Identification		
Weed genus and species	<i>B. tectorum</i>	<i>L. latifolius</i>
Weed common name(s)	Cheat grass	Perennial Sweet Pea (minor)
	Klamath Weed	Bull Thistle
Presence		
Presence or Absence	Present (all)	
Treated	Yes	(chemical and mechanical)
Infested area	12,000 sq. ft.	
Canopy Cover	<1%	<1%
Appearance	New growth	<1%
Distribution pattern	Scattered patchy	<1%
Photo documentation	Linear	<1%
	724,730	
Weed Location		
Geographic location (ID)	L21-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	<1m	Along beginning of Camp P road, near intersection with 10N40N; extends for about 600'(ft) along road. 2011 Update: Very good control all species <1%; VETH coming back but treated; actively growing patches of LALA4 on adj. SPI land.
Location description		

General Information			ID: L22-08
Collection date (mm/dd/yyyy)	Ethan Koenigs		7/1/2011
Observer name(s)			
Site or facility name	Access Road	Site Information	
Site address or other description	Rock Crusher road		
Ownership	USFS/SPI		
Land use type	Transportation Corridor		
Invaded vegetation type	Forest		
Gross Area	0.5 acres		
Disturbances & impacts	Roadside maintenance	SPI plantation	
Associated species			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Mixed Conifer, Deer Brush, weedy species along road.		
	Full sun; western exposure		
Weed Information			Weed Identification
Weed genus and species	<i>Cirsium vulgare</i> , <i>H. perforatum</i>	<i>Bromus tectorum</i>	<i>Melilotus alba</i>
Weed common name(s)	Bull Thistle, Klamath Weed	Cheat Grass	White Sweet Clover
Presence			Verbasium thapsoides
Presence or Absence	Present (not all species)	No VETH or HYPE	Woolly Mullein
Treated	Yes	11,000 sq. ft.	
Infested area		<1%	<1%
Canopy Cover		New growth	
Distribution pattern	New growth	Seedling	
Photo documentation	Scattered patchy	Linear	Clumpy
		710	
Weed Location			
Geographic location (ID)	L22-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	< 1m		Linear stretch from gate all along SPI plantation to top of hill and FS boundary. 2011 Update: Recent treatment.
Location description			

General Information			ID: L23-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/1/2011	
Observer name(s)			Site Information
Site or facility name	Access Road		
Ownership	Camp P Road		
Land use type	Transportation Corridor		
Invaded vegetation type	Forest	500 sq. ft.	
Gross Area	Canal Maintenance		
Disturbances & impacts			
Associated species	Mixed Conifer; Big-leaf Maple; grasses & forbs		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	NW exposure		
Weed Information			Weed Identification
Weed genus and species	<i>Cirsium vulgare</i>	<i>Torilis arvensis</i>	
Weed common name(s)	Bull Thistle	Hedge Parsley	
Presence or Absence	Present (all)		Presence
Treated	Yes	500 sq. ft.	
Infested area	<1%	<1%	
Canopy Cover	New growth	Flowering	
Distribution pattern	Clumpy	Clumpy	
Photo documentation	717		Weed Location
Geographic location (ID)	L23-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	1-5m		
Location description	Just before bend in the road (heading down slope) small turnout on north side; minor occurrence. 2011 Update: CIVU and TOAR appear to be coming back from 2010, but sprayed this year.		

General Information		ID: L24-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/1/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Camp P Road	
Ownership		
Land use type		
Invaded vegetation type	Transportation Corridor	
Gross Area	Forest	
Disturbances & impacts	200 sq. ft.	
Associated species	Roadside maintenance	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Mixed Conifer; Big-Leaf Maple, Dogwood Shady, NW exposure	
Weed Information		Weed Identification
Weed genus and species	<i>Torilis arvensis</i>	
Weed common name(s)	Hedge Parsley	
Presence or Absence	Present (all)	
Treated	Yes	
Infested area	200 sq. ft.	
Canopy Cover	1-5%	
Distribution pattern	Flowering	
Photo documentation	Scattered patchy 714, 715	
Weed Location		
Geographic location (ID)	L24-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Near end of road; 500' to gate; immediately after graded area, scattered TOAR extends to larger Doug fir past bend in road.	

General Information		ID: L25-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/1/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Camp 2 Road	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	900 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	Mixed Conifer	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Gravel shoulder along road - moderately dense forest - flat.	
Weed Information		Weed Identification
Weed genus and species	<i>Cirsium vulgare</i>	
Weed common name(s)	Bull Thistle	
Presence or Absence	Present (all)	
Treated	No	
Infested area	900 sq. ft.	
Canopy Cover	<1%	
Appearance	New growth	
Distribution pattern	Scattered patchy	
Photo documentation	705-706	
Weed Location		
Geographic location (ID)	L25-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Primarily east side of road near small drainage. very minor occurrence. 2011 Update: Slightly fewer CIVU.	

**APPENDIX C****EID Weed Observation and Monitoring Form****Canal Beats 2, 3 & small section of Beat 4**

<b>Photo Log</b>			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
576, 577	06-09	S/SW	CIVU near canal; RUAR9 below flume spillway
578	L05-11	SW	Patch of TOAR near canal, Beat 3
579	L06-11	SW	Good control of LALA4 below flume
580	L06-11	SE	LALA4 returning in places below flume
581/583	L06-11	SE	Good control of RUAR9 / LALA4 returning
582	L06-11	SE	Access road terminus at spillway (Camp P) – partial control of LALA4
584	26-08	SW	Good control of RUAR9 here
585	05-09	S	Esmeralda Flume; scattered HYPE, CIVU - recently sprayed
586	50-08	W	LEVU near Alarm 15
587	25-08	W	Recently sprayed CIVU - good control
588	09-09	E	BRTE near Plum Siphon, on Beat 2
589	02-11	W	Small patch of RUAR9 below new flume on Beat 2
<b>Notes</b>			

General Information		ID: 02-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/7/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Ownership	Beat 2	
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	2,500 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species	Doug fir, Dogwood, Cedar, Maple, var. grasses	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	In swale, north facing slope; recently disturbed/graded	
Weed Information		Weed Identification
Weed genus and species	<i>Rubus armeniacus</i>	<i>Cirsium vulgare</i>
Weed common name(s)	Himalayan blackberry	Bull thistle
Presence or Absence	Present (all)	Presence
Treated	No	
Infested area	150 sq. ft.	
Canopy Cover	1-5%	<1%
Appearance	New growth	New growth
Distribution pattern	Clumpy	Clumpy
Photo documentation	589	
Weed Location		
Geographic location (ID)	02-11	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1-5m	
Location description	Below new flume section; two CIVU plants on opposite side of new flume; small patch of RUAR9 growing through geo-textile fabric.	

General Information		ID: 05-09
Collection date (mm/dd/yyyy)	Ethan Koenigs,	7/7/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Beat 4 at Esmerelda Crk. Flume over canal	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	1000 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species	Mixed Conifer and Montane Riparian; bracken fern, native blackberry, mixed grasses & forbs.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Riparian area	
Weed Information		Weed Identification
Weed genus and species	<i>Leucanthemum vulgare</i>	<i>Cirsium vulgare</i>
Weed common name(s)	Ox-eye Daisy	Klamath weed
		Bull thistle
Presence or Absence	Present (all)	Presence
Treated	Yes	
Infested area	1000 sq. ft.	
Canopy Cover	<1%	
Appearance	Flowering	New growth
Distribution pattern	Scattered patchy	New growth
Photo documentation	585	
Weed Location		
Geographic location (ID)	05-09	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	5-15m	
Location description	Near propane tank & creek flume at tunnel exit. 2011 Update: Recently sprayed; small patch of Ox-eye on east side of concrete drainage ditch; plants are dying, appears to be good control (sprayed).	

General Information		ID: 06-09
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/7/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Beat 3	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	800 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Mixed Conifer-hardwoods; Douglas Fir, Incense Cedar, Black Oak, Dogwood, yarrow, mixed annual grasses.  Shady, north-facing slope.	
Weed Information		Weed Identification
Weed genus and species	<i>Cirsium vulgare</i>	<i>Rubus armeniacus</i>
Weed common name(s)	Bull Thistle	Himalayan Blackberry
Presence or Absence	Present (all)	Presence
Treated	No	
Infested area	200 sq. ft.	
Canopy Cover	1-5%	
Appearance	New growth	
Distribution pattern	Clumpy	
Photo documentation	576, 577	
Weed Location		
Geographic location (ID)	06-09	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	5-15m	
Location description	On bench north of canal, near rock pile and just downstream of spillway. Very minor occurrence. 2011 Update: About Six CIVU; a few CIVU and RUAR9 under spillway along drainage.	

General Information		ID: 09-09
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/7/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Beat 2, Plum Creek siphon entrance	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	1500 sq. ft.	Maintained area around spillway and siphon entrance
Disturbances & impacts		
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Mixed Conifer - other weedy species Open & exposed-disturbed gravelly soil.	
Weed Information		Weed Identification
Weed genus and species	<i>Bromus tectorum</i>	
Weed common name(s)	Cheat grass	
Presence or Absence	Present (all)	Presence
Treated	Yes	
Infested area	500 sq. ft.	
Canopy Cover	<1%	
Appearance	Senesc.	
Distribution pattern	Seeding	
Photo documentation	Linear	
	588	Weed Location
Geographic location (ID)	09-09	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	Along canal, between spillway and entrance to siphon. 2011 Update: Partial control, maybe from treatment last fall; mostly gone along fence and canal; very minor occurrence.
Location description		

General Information		ID: 25-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/7/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Spur Road north of 10N40N, just past old Camp 4 bridge.	
Ownership		
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	1,200 sq. ft.	
Disturbances & impacts	Roadside maintenance	Other man-made disturbance
		Large landing adjacent
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Ponderosa Pine, Sugar Pine, Black Oak, Douglas Fir, Grasses	
Weed Information		Weed Identification
Weed genus and species		
Weed common name(s)		
Presence or Absence	Present (all)	
Treated	Yes	
Infested area	1,200 sq. ft.	
Canopy Cover	<1%	
Appearance	New growth	Dead
Distribution pattern	Scattered patchy	
Photo documentation	587	
Weed Location		
Geographic location (ID)	25-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Spur road off of Hazel Valley Road - large clearing next to road. 2011 Update: Recently treated; good targeting of CIVU; very few CIVU actively growing.	

General Information		ID: 26-08	
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/7/2011	
Observer name(s)			
Site or facility name	El Dorado Canal	Site Information	
Site address or other description	Beat 3		
Ownership			
Land use type	Water Transport Facility		
Invaded vegetation type	Forest		
Gross Area	500 sq. ft.		
Disturbances & impacts	Canal Maintenance		
Associated species			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Big leaf maple, Thimbleberry, Canyon Live Oak, Douglas Fir, Incense Cedar Very exposed, northwest facing slope, rocky soil.		
Weed Information		Weed Identification	
Weed genus and species	<i>Rubus armeniacus</i>		
Weed common name(s)	Himalayan Blackberry		
Presence or Absence	Present (all)	Presence	
Treated	Yes		
Infested area	50 sq. ft.		
Canopy Cover	<1%		
Appearance	New growth		
Distribution pattern	Clumpy		
Photo documentation	584		
Weed Location			
Geographic location (ID)	26-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	< 1m		
Location description	Clump of Himalayan blackberry below flume; steep slope. 2011 Update: Same as 2010 - area treated, small patch remaining		

General Information		ID: 50-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/7/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Beat 4 near Esmeralda Tunnel	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	750 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species	Mixed Conifer, Montane Riparian; native blackberry; other weedy species	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Disturbed	
Weed Information		Weed Identification
Weed genus and species	<i>Leucanthemum vulgare</i>	
Weed common name(s)	Ox-eye Daisy	
Presence or Absence	Present (all)	Presence
Treated	No	
Infested area	750 sq. ft.	
Canopy Cover	1-5%	
Distribution pattern	Flowering	
Photo documentation	Scattered even	Linear
	586	Weed Location
Geographic location (ID)	50-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	On the north side of canal near spillway 30 (Esmeralda Creek). 2011 Update: LEVU Coming back between spillway and Esmeralda .
Location description		

General Information		ID: L05-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/7/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Canal Beat 3	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	2,500 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species	Mixed Conifer-hardwoods; Douglas Fir, Incense Cedar, Black Oak, Dogwood, big leaf maple, mixed annual grasses.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Near riparian zone	
Weed Information		Weed Identification
Weed genus and species	<i>Torilis arvensis</i>	
Weed common name(s)	Hedge Parsley	
Presence or Absence	Present (all)	Presence
Treated	No	
Infested area	2,500 sq. ft.	
Canopy Cover	5-25%	
Appearance	Flowering	
Distribution pattern	Scattered even	
Photo documentation	578	Wed Location
Geographic location (ID)	L05-11	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1-5m	
Location description	Near a small drainage along Beat 3. Minor occurrence of TOAR -in riparian no spray zone.	

General Information		ID: L06-11
Collection date (mm/dd/yyyy)	7/7/2011	Previously Identified L18-08, L19-08, 27-08, 28-08
Observer name(s)	Ethan Koenigs	
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Beat 3	
Ownership	Water Transport Facility	
Land use type	Forest	
Invaded vegetation type		
Gross Area	0.25 acres	
Disturbances & impacts	Canal Maintenance	Other man-made disturbance
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Mixed Conifer & Hardwood - Incense Cedar, Canyon Live Oak, Thimbleberry, Black Oak; Montane riparian as well. West facing slope near Ogilby Creek.	
Weed Information		Weed Identification
Weed genus and species	<i>Lathyrus latifolius</i>	<i>Rubus armeniacus</i>
Weed common name(s)	Perennial Sweet Pea	Himalayan Blackberry
Presence or Absence	Present (all)	Presence
Treated	Yes	
Infested area	0.15 acres	
Canopy Cover	5-25%	<1%
Distribution pattern	Flowering	New growth
Photo documentation	Clumpy	Linear
Geographic location (ID)	L06-11	Weed Location
Coordinate system	previously included the following occurrences: L18-08, L19-08, 27-08, 28-08 Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	<1m	

Linear stretch on downslope side of flume up to the end of access road near alarm station on Oggiby Creek. 2011 Update: Partial control; LALA4 returning; RUAR9 under control, but a few plants remain in riparian zone; recently sprayed near access road; five clumps of RUAR9 on West side of spillway building.
Location description

**APPENDIX C**

**EID Weed Observation and Monitoring Form – Lower Penstock, portion of Upper  
Penstock, Forebay, Bend Court access road**

<b>Photo Log</b>			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
590	L01-09	W	RUAR9 along pathway up penstock, good control
591	L01-09	S	Good control of RUAR9 along penstock
592,593	L01-09	S	VETH, CIVU, and HYPE along w. side of penstock
594, 596	11-08	W	Treated area; RUAR9 and HYPE adjacent to penstock and structure
597	L07-11	N	Treated area above 11-08; RUAR9, HYPE
598	L07-11	N	CHJU scattered along penstock, near tracks
599	02-09	N-NE	MEOF near surge chamber - sprayed and dying
600	L2-09	E	HYPE near penstock
601	46-08	NE	Few scattered LALA4 – parking lot of Forebay
602	L08-11	E	HYPE and LEVU along shore at Forebay
604, 605	L06-08	E/W	CYSC4 at Forebay - good control - a few seedlings remain
606, 607	L04-09	SE/SE	CIVU, LEVU, HYPE along lake shore; recent removal of blackberry
609, 610, 611	L05-09	S/E/SE	HYPE and LEVU along shore/heavy RUAR9 along lake
612, 613	*Area 1	S/SW	Mustard along Dam; LALA 4 in background along road down to penstock
614, 615	14-08	S/N	Scattered BRTE at top of hill;
616	L09-11	SW	Blackberry near creek at end of Bend Ct. road
617	L09-11	NE	Scattered TOAR and other weeds along end of Bend Ct. road
<b>Notes</b>			
* Area 1 data sheet included in 6/22/11 folder			

General Information			ID: 02-09
Collection date (mm/dd/yyyy)	Ethan Koenigs	Chad Johnson	7/14/2011
Observer name(s)			
Site or facility name	EID Penstock	Site Information	
Site address or other description	Surge Chamber		
Ownership			
Land use type	Water Transport Facility		
Invaded vegetation type	Forest		
Gross Area	250 sq. ft.		
Disturbances & impacts	Pipe Maintenance	Roadside maintenance	
Associated species	Manzanita, Ponderosa Pine		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Gravel road at dead end.		
Weed Information			Weed Identification
Weed genus and species	<i>Meliolotus officinalis</i>		
Weed common name(s)	White Sweet Clover		
Presence or Absence	Present (all)		Weed Description
Treatment	Yes		
Infested area	250 sq. ft.		
Canopy Cover	5-25%		
Distribution pattern	Dead		
Photo documentation	Clumpy		
	599		Weed Location
Geographic location (ID)	02-09		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	<1m		
Location description	Small patch of sweet clover at surge chamber. 2011 Update: Recently sprayed; good control.		

General Information				ID: 11-08
Collection date (mm/dd/yyyy)	7/14/2011			
Observer name(s)	Ethan Koenigs			
Site Information				
Site or facility name	EID Penstock			
Site address or other description	Lower penstock (steep portion)			
Ownership				
Land use type	Forest			
Invaded vegetation type	Water Transport Facility			
Gross Area	0.25 acres			
Disturbances & impacts	Canal Maintenance			
Associated species	Trail Maintenance			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Douglas fir , Canyon Live Oak, Deer Brush, Toyon Exposed, northwest-facing slope			
Weed Information				
Weed genus and species	<i>Rubus armeniacus</i>	<i>Verbascum thapsus</i>	<i>Bromus tectorum</i>	<i>Hypericum perforatum</i>
Weed common name(s)	Himalayan blackberry	Woolly Mullein	Cheat grass	Klamath weed
Weed Description				
Presence or Absence	Present (all)			
Treatment	Yes			
Infested area	2,000 sq. ft.			
Canopy Cover	<1%	5-25%	<1%	5-25%
Appearance	Flowering	Senesc.	Flowering	New growth
Distribution pattern	Clumpy	Scattered patchy	Clumpy	Scattered even
Photo documentation	594, 596, 597			
Weed Location				
Geographic location (ID)	11-08			
Coordinate system	Ca. State Plane Zone 2			
Datum	NAD83			
Location data accuracy	< 1m			
Location description	Clump of RUAR9 near water tank in lower section of Penstock and scattered clumps of VETH and HYPE. Increasing.			
2011 Update: Knocked-back RUAR9; BRTE & CHJU				

General Information		ID: 14-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/14/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Bend Court	Near top of road
Ownership		
Land use type		
Invaded vegetation type		
Gross Area	Transportation Corridor Forest	
Disturbances & impacts	1,200 sq. ft.	
Associated species	Roadside maintenance	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Ponderosa Pine, Black Oak, Deer Brush, Annual Grasses, and Forbes (yellow bur navarretia).	
Weed Information		Weed Identification
Weed genus and species	<i>Bromus tectorum</i>	
Weed common name(s)	Cheat grass	
Presence or Absence	Present (all)	
Treated	No	
Infested area	1,200 sq. ft.	
Canopy Cover	5-25%	
Appearance	New growth	
Distribution pattern	Scattered even	
Photo documentation	614,615	
Weed Location		
Geographic location (ID)	14-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Area at top of hill in a clearing and along roadway. Rare Plant-Yellow bur navarretia is present throughout area. <u>No Treatment</u> ; 2011: cheat grass still present.	

General Information		ID: 46-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/14/2011
Observer name(s)		
Site or facility name	Forebay Reservoir	Site Information
Site address or other description	Day use area parking	
Ownership	Water Storage Facility	
Land use type	Forest	
Invaded vegetation type		
Gross Area	0.25 acres	
Disturbances & impacts	Facility Maintenance	Roadside maintenance
Associated species	Ponderosa Pine, Incense Cedar, Deer Brush, Black Oak	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	High impact site; thick layer of pine needle litter.	
Weed Information		Weed Identification
Weed genus and species	<i>Hypericum perforatum</i>	<i>Lathyrus latifolius</i>
Weed common name(s)	Klamath Weed	Perennial Sweet Pea
Presence or Absence	Present (not all species)	Presence
Treated	Yes	Klamath Weed (absent)
Infested area		5000 sq. ft.
Canopy Cover	<1%	1-5%
Appearance	Flowering	New growth
Distribution pattern	Scattered even	
Photo documentation	601	Weed Location
Geographic location (ID)	46-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	Area between day use parking and Forebay road. 2011 Update: Sweet pea diminished; Klamath weed absent;
Location description		

General Information		ID: L01-09
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/14/2011
Observer name(s)		
Site Information		
Site or facility name	Penstock	
Site address or other description	Lower section, Near Powerhouse	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	1 acres	
Disturbances & impacts	Canal Maintenance	Trail Maintenance
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Douglas fir , Canyon Live Oak, Deer Brush, Toyon  Exposed, northwest-facing slope	
Weed Information		
Weed Identification		
Weed genus and species	<i>Rubus armeniacus</i>	<i>Chondrilla juncea</i>
Weed common name(s)	Himalayan blackberry	Rush Skeletonweed
Weed Description		
Presence or Absence	Present (all)	
Treated	Yes	
Infested area	5000 sq. ft.	
Canopy Cover	5-25%	5-25%
Seeding	Flowering	Seeding
Distribution pattern	Scattered patchy	Linear
Photo documentation	590, 591, 592, 593	
Weed Location		
Geographic location (ID)	L01-09	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	Trail from Powerhouse up to Penstock; scattered along trail and Penstock approx. 300ft. 2011 Update: Good control on lower half; top half weeds are repopulating, especially skeleton weed; lesser wooly mullein; Klamath weed and cheat grass are scattered; blackberry encroaching from periphery of control.	

General Information		
Collection date (mm/dd/yyyy)	Ethan Koenigs	C. Johnson
Observer name(s)	Site Information	
Site or facility name	EID Penstock	Between Surge Chamber and
Ownership	Water Transport Facility	
Land use type	Forest	
Invaded vegetation type	Pipe Maintenance	1 acres
Gross Area		
Disturbances & impacts		
Associated species		Mixed Conifer - Ponderosa Pine, Douglas fir , Big Leaf Maple, Manzanita
Environmental Conditions (e.g. soil conditions, exposure, etc.)		Steep East facing canyon slope. Dry and rocky soil.
Weed Information		
Weed genus and species	<i>Hypericum perforatum</i>	Weed Identification
Weed common name(s)	Klamath Weed	
Presence or Absence	Present (all)	
Treatment	No	
Infested area	0.2 acres	
Canopy Cover	<1%	
Appearance	Seeding	
Distribution pattern	Scattered even	
Photo documentation	600	
Weed Location		
Geographic location (ID)	LO2-09	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	<1m	Primarily on north side of pipe, along <i>both</i> sides of access road, from end of Moon Lane East, east toward tunnel. 2011
Location description	Update: Increasing Klamath weed; large patches in middle of line segment.	

General Information		ID: L04-09
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/14/2011
Observer name(s)	C. Johnson	
Site or facility name	Forebay Reservoir	Site Information
Site address or other description	Along lake shore, northeast side.	
Ownership		
Land use type	Water Storage Facility	
Invaded vegetation type	Forest	
Gross Area	0.3 acres	Lake fluctuation
Disturbances & impacts	Other man-made disturbance	
Associated species	Ponderosa Pine, Incense Cedar, Black Oak, Alder, Native Blackberry.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Sunny, exposed, west-facing, along lake shore	
Weed Information		Weed Identification
Weed genus and species	<i>Cirsium vulgare</i> , <i>Hypericum perforatum</i> , <i>Leucanthemum vulgare</i> , <i>Lathyrus latifolius</i> , <i>Verbascum thapsus</i>	
Weed common name(s)	Bull Thistle, Klamath Weed Ox-eye Daisy	Perennial Sweet Pea, wooly mullein
Presence		
Presence or Absence	Present (all)	
Treated	Yes	
Infested area	4000 sq. ft.	
Canopy Cover	<1% Flowering Clumpy	1-5% Flowering Linear
Distribution pattern		Scattered even
Photo documentation	606, 607, 608	Scattered patchy
Weed Location		
Geographic location (ID)	L04-09	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description & Comments	Northeast side of lake along shore. Very close to edge of water. 2011 Update: Last 1/10 NW portion of line not effectively treated; the rest looks good.	

General Information		ID: L05-09
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/14/2011
Observer name(s)	C. Johnson	
Site Information		
Site or facility name	Forebay Reservoir	
Site address or other description	northeast side of reservoir	
Ownership		
Land use type	Water Storage Facility	
Invaded vegetation type	Forest	
Gross Area	0.35 acres	Lake fluctuations
Disturbances & impacts	Other man-made disturbance	
Associated species	Ponderosa Pine, Native Blackberry, Cherry Tree, Alder, Willow	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Sunny, west facing, in clearing.	
Weed Information		
Weed Identification		
Weed genus and species	<i>Rubus discolor</i>	<i>Leucanthemum vulgare</i>
Weed common name(s)	Himalayan Blackberry	Ox-eye Daisy
Presence		
Presence or Absence	Present (all)	
Treated	No	
Infested area	0.3 acres	
Canopy Cover	25-50%	5-25%
Appearance	Flowering	Flowering
Distribution pattern	Linear	Scattered patchy
Photo documentation	609, 610, 611	Scattered even
Weed Location		
Geographic location (ID)	L05-09	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	

Location description	Lake shore, RUAR9 forms a dense band along the shore; approximately 50'. 2011 Update: RUAR9 interspersed with native blackberry; similar to last year; scattered patchy RUAR9 and scattered even daisy along shoreline into Forebay inlet (see Photo 611). ox eye continues around shoreline on south side of reservoir
----------------------	---

General Information			ID: L06-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	C. Johnson	7/14/2011
Observer name(s)			
Site or facility name	Forebay Reservoir		Site Information
Site address or other description	Trail on North side of reservoir		
Ownership			
Land use type	Water Storage Facility		
Invaded vegetation type	Forest	2000 sq. ft.	
Gross Area	Trail Maintenance	Other man-made disturbance	
Disturbances & impacts			
Associated species	Ponderosa Pine, Incense Cedar, Deer Brush, Black Oak		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Heavy pine needle litter/ partly shaded		
Weed Information			Weed Identification
Weed genus and species	<i>Cytisus scoparius</i>		
Weed common name(s)	Scotch Broom		
Presence or Absence	Present (not all species)	No sweet pea	Presence
Treated	Yes		
Infested area		200 sq. ft.	
Canopy Cover	<1%		
Appearance	New growth		
Distribution pattern	Clumpy		
Photo documentation	604, 605		
Weed Location			
Geographic location (ID)	L06-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	< 1m		
Location description	Approximately 50' from day-use area entrance. 2011 Update: Aggressive, recent control appears to be effective.		

General Information		L07-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/14/2011
Observer name(s)		Site Information
Site or facility name	EID Penstock	
Site address or other description	Lower penstock bottom edge of line above 11-08; top edge at second penstock foundation block.	
Ownership	Water Transport Facility	
Land use type	Forest	
Invaded vegetation type		
Gross Area	0.5 acres	
Disturbances & impacts	Canal Maintenance	
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Douglas fir , Canyon Live Oak, Deer Brush, Toyon  Exposed, northwest-facing slope	
Weed Information		Weed Identification
Weed genus and species	<i>Rubus armeniacus</i>	<i>Bromus tectorum</i>
Weed common name(s)	Himalayan blackberry	Cheat grass
	Woolly Mullein	<i>Hypericum perforatum</i>
		Klamath weed
Weed Description		Chondrilla juncea Skeleton Weed
Presence or Absence	Present (all)	
Treatment	Yes	
Infested area	20,000 sq. ft.	
Canopy Cover	<1%	1-5%
Appearance	Flowering	Senesc.
Distribution pattern	Clumpy	Scattered even
Photo documentation	597, 598	Clumpy
Weed Location		
Geographic location (ID)	L07-11	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1-5m	
Location description	West side of penstock, CHIU and RUAR9 increasing; overall occurrences are increasing.	

General Information		L08-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/14/2011
Observer name(s)		
Site Information		
Site or facility name	Forebay Reservoir	
Site address or other description	Beach near day-use parking	
Ownership	EID	
Land use type	Water Storage Facility	
Invaded vegetation type	Forest	
Gross Area	5500 sq. ft.	
Disturbances & impacts	Facility Maintenance	Other man-made disturbance
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Exposed south-facing shoreline of reservoir; bare soil	
Weed Information		Weed Identification
Weed genus and species	<i>Hypericum perforatum</i>	<i>Leucanthemum vulgare</i>
Weed common name(s)	Klamath weed	Ox-eye daisy
Presence or Absence		Weed Location
Treatment	Present (all)	
Infested area	Yes	
Canopy Cover	3,000 sq. ft.	
Appearance	1-5%	
Distribution pattern	Flowering	
Photo documentation	Scattered patchy	
	602	
Geographic location (ID)	L08-11	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1-5m	
Location description	Area along shore at Forebay, just below picnic area. Weeds along high water mark extending to day-use parking in thickest infestation area.	

General Information		L09-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/14/2011
Observer name(s)		
Site Information		
Site or facility name	Access Road	
Site address or other description	Bend Ct (between landing and stream crossing at end)	
Ownership		
Land use type	Forest	
Invaded vegetation type	Transportation Corridor	
Gross Area	13,500 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Cedar, maple, ponderosa, doug fir, black oak, yarrow, tincture plant, soap lily, clarkia sp., grasses dirt road, recently graded	
Weed Information		
Weed genus and species	<i>Hypericum perforatum</i>	<i>Rubus armeniacus</i>
Weed common name(s)	Klamath weed	Hedge Parsley
Presence or Absence	Present (all)	
Treatment	Yes	
Infested area	7,500 sq. ft.	
Canopy Cover	<1%	1-5%
Appearance	New growth	Flowering
Distribution pattern	Scattered patchy	Clumpy
Photo documentation	616, 617	Scattered patchy
Weed Location		
Geographic location (ID)	L09-11	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1-5m	
Location description	Lower portion of Bend Court access road near canal and small perennial drainage; line extends beyond mapped access road.	

## APPENDIX C

### EID Weed Observation and Monitoring Form

#### Diversion Dam, Canal-Beat 1, Roads near Camp 1

<b>Photo Log</b>			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
622, 623	47-08	NE/W	Multiple weeds to east of intake facility / LALA4 abundant
624	47-08	E	Multiple weeds to east of intake facility
625, 626	41-08	W	Weed control near canal intake/some LALA4
627, 628	41-08	W	Weeds in rip rap near fish ladder
629, 630	40-08	W/SW	LEVU and VETH along flume
631	48-08	E	Few LEVU
632	10-09	NW	Good control of HYPE, one small patch along fence
633	06-10	SE	Patch of dense HYPE
634,635,	L35-08	W/W	Large patch of VETH below flume/ abundant mugwort mixed in
636, 637	L35-08	W/SE	Weedy; CHJU, BRTE
638, 639, 640	L34-08	NW	Star thistle here**, VETH, BRTE, CIVU; Esp. weedy outside fence (VETH)
645	L10-11	SE	Clump of VETH along canal
646,	L33-08	SE	VETH and BRTE on east end of line
647, 648	L33-08	NW	HYPE & VETH along canal and outside fence
649, 650	38-08	W/SW	LALA4 along canal
651, 652	L29-08	W/E	Good control - mostly BRTE along rd.
653	37-08	SW	Patch of BRDID2 and BRTE on road shoulder
654	L29-08	W	MEOF in turnout area/ edge sprayed & dying

Photo Log			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
655	39-08	NW	Clearing surrounded by dead, sprayed weeds - good control
656	L32-08	W	Weeds sprayed along shoulder of upper Camp 1 canal access road;
657	L30-08	S	LALA4 below drive leading to Camp 1 house; edge of rd. sprayed
658	L30-08	N	Very minor BRTE along road; recently sprayed
659	36-08	S	Good control – no noxious weeds
660	L28-08	NE	MEOF along road, Alder crk. bridge - recently sprayed, dying
661	L28-08	N	Dying weeds along shoulder, mostly MEOF
662, 663	L28-08	NW/NE	Upper end - MEOF dying; good control along edge of road
664, 665	L26-08	S / N	Good control along "old" section of road to S / good control in large turnout
666, 667	L26-08	N-NW	dense BRDID2 and BRTE on down slope and around margin at road end
668	L27-08	NW	Minor BRTE, VETH, MEOF, HYPE and other weeds
Notes			
Page 2			

General Information		ID: 06-10
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Beat 1	
Ownership	Water Transport Facility	
Land use type	Forest	
Invaded vegetation type	300 sq. ft.	
Gross Area	Canal Maintenance	
Disturbances & impacts		
Associated species	Sierran Mixed conifer; big leaf maple, grasses	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	NW Exposure, rocky soil, near a small drainage	
Weed Information		Weed Identification
Weed genus and species	<i>Hypericum perforatum</i>	
Weed common name(s)	Klamath weed	
Presence or Absence	Present (all)	Presence
Treated	No	
Infested area	300 sq. ft.	
Canopy Cover	5-25%	
Appearance	Flowering	
Distribution pattern	Clumpy	
Photo documentation	633	
Weed Location		
Geographic location (ID)	06-10	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1.5m	
Location description	Near a mini tunnel that canal passes through; next to a small drainage; minor occurrence. 2011 Update: Same as 2010.	

General Information		ID: 10-09
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Beat 1	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	2,000 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species	Big leaf maple, black oak, ponderosa pine, annual grasses	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Near a small drainage	
Weed Information		Weed Identification
Weed genus and species	<i>Hypericum perforatum</i>	
Weed common name(s)	Klamath Weed	
Presence or Absence	Present (all)	Present (not all species)
Treated	Yes	
Infested area	25 sq. ft.	
Canopy Cover	<1%	
Appearance	Flowering	
Distribution pattern	Clumpy	
Photo documentation	632	
Weed Location		
Geographic location (ID)	9-Oct	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1.5m	
Location description	W. side of small bridge over drainage; 2011 Update: Same as last year; few more HYPE coming in, but overall very light occurrence	

General Information		ID: 36-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011
Observer name(s)		
Site or facility name	Access Road	Site Information
Site address or other description	El Dorado Tunnel Road	
Ownership	Transportation Corridor	
Land use type	Forest	
Invaded vegetation type	Roadside maintenance	400 sq. ft.
Gross Area		Turnout in road
Disturbances & impacts		
Associated species	Ponderosa Pine, Douglas Fir, Blue Wild Rye, Alder, Big Leaf Maple, Willows	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Flat area, near Alder Creek	Weed Information
		Weed Identification
Weed genus and species	Meliolotus officinalis	Bromus tectorum
Weed common name(s)	White Sweet Clover	Cheat grass
		Present (not all species)
Presence or Absence	Absent	
Treated	Yes	
Infested area		0 sq. ft.
Canopy Cover	<1%	
Appearance	New growth	Seeding
Distribution pattern	Scattered even	
Photo documentation	659	
		Weed Location
Geographic location (ID)	36-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	<1m	El Dorado Tunnel road, 100' from gate & near siphon; <b>within 100' of Alder Crk.</b> 2011 Update: No weeds observed.
Location description		

General Information			ID: 37-08
Collection date (mm/dd/yyyy)	Ethan Koenigs,	Logan McCarthy	7/21/2011
Observer name(s)			
Site or facility name	Access Road	Camp 1 road	Site Information
Site address or other description	Transportation Corridor		
Ownership	Forest	250 sq. ft.	
Land use type	Roadside maintenance		
Invaded vegetation type			
Gross Area			
Disturbances & impacts			
Associated species	Black Oak, Douglas fir, Incense Cedar, Deer Brush, Yarrow		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	gravel road		
Weed Information			Weed Identification
Weed genus and species	<i>Bromus tectorum</i>	<i>Melilotus officinalis</i>	<i>Bromus diandrus</i>
Weed common name(s)	Cheat grass	White Sweet Clover	Ripgut Brome
Weed Description			Weed Description
Presence or Absence	Present (not all species)	MEOF (absent)	
Treated	Yes		
Infested area	250 sq. ft.		
Canopy Cover	1-5%	1-5%	
Appearance	New growth		Senesc.
Distribution pattern	Clumpy		
Photo documentation	653		
Weed Location			
Geographic location (ID)	37-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	<1m		
Location description	West side of road, half-way up. Sweet clover very minimal, mostly ripgut and cheat grass. 2011 Update: Same as 2010 except no MEOF.		

General Information		ID: 38-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011
Observer name(s)		
Site or facility name	El Dorado Canal	Site Information
Site address or other description	Beat 1	
Ownership	Water Transport Facility	
Land use type	Forest	
Invaded vegetation type	Canal Maintenance	300 sq. ft.
Gross Area		Other man-made disturbance
Disturbances & impacts		
Associated species	Mixed conifer; Bracken Fern	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	NW Exposure	
Weed Information		Weed Identification
Weed genus and species	<i>Lathyrus latifolius</i>	<i>Cytisus scoparius</i>
Weed common name(s)	Perennial Sweet Pea	Scotch Broom
Presence or Absence	Present (not all species)	Presence
Treated	No	(CYSC4 absent)
Infested area	300 sq. ft.	
Canopy Cover	1-5%	
Appearance	Flowering	
Distribution pattern	Clumpy	
Photo documentation	649, 650	
Weed Location		
Geographic location (ID)	38-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1.5m	
Location description	Near Camp 1 at entrance to Alder Creek Siphon; mostly on north side of canal along fence line; small area on south side of canal. 2011 Update: Same as 2010	

General Information		ID: 39-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011
Observer name(s)		
Site or facility name	Access Road	
Site address or other description	Camp 1 road (East fork of roa	
Ownership	Transportation Corridor	Water Transport Facility
Land use type	Forest	
Invaded vegetation type	3500 sq. ft.	
Gross Area	Roadside maintenance	Other man-made disturbance
Disturbances & impacts		
Associated species	Ponderosa Pine, Douglas Fir, Black Oak, Deer Brush, Blue Wild Rye, Curly Dock	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Northwest-facing slope, rocky soil, very exposed	
Weed Information		Weed Identification
Weed genus and species	Meliolotus officinalis	Bromus tectorum
Weed common name(s)	Sweet Clover	Cheat Grass
		Present
Presence or Absence	Present (all)	
Treated	Yes	
Infested area	1000 sq. ft.	
Canopy Cover	<1%	1-5%
Appearance	New growth	Senesc.
Distribution pattern	Clumpy	Scattered patchy
Photo documentation	655	
Weed Location		
Geographic location (ID)	39-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	<1m	
Location description	Large clearing; weeds primarily around the margin. 2011 Update: Good control of MEOF, dying.	

General Information		ID: 40-08	
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011	
Observer name(s)			
Site or facility name	El Dorado Canal	Site Information	
Site address or other description	Beat 1		
Ownership			
Land use type	Water Transport Facility		
Invaded vegetation type	Forest		
Gross Area	1000 sq. ft.		
Disturbances & impacts	Canal Maintenance		
Associated species	Montane Riparian; Mixed Conifer		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	sandy soil		
Weed Information		Weed Identification	
Weed genus and species	<i>Leucanthemum vulgare</i>	<i>Verbascum thapsus</i>	
Weed common name(s)	Ox-eye Daisy	Wooly Mullein	
		<i>Hypericum perforatum</i>	
		Klamath Weed	
Presence or Absence		Presence	
Treated	Present (all)		
Infested area	No		
Canopy Cover	700 sq. ft.		
Appearance	<1%		
Distribution pattern	Flowering		
Photo documentation	Scattered even		
	Clumpy		
	629, 630		
Weed Location			
Geographic location (ID)	40-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	1-5m		
Location description	Near Flume 1. LEVU on both sides of canal. 2011 Update: Same as 2010; HYPE on south side of canal; LEVU increased, especially on south side of canal; VETH static.		

General Information		Site Information						
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011						
Site or facility name		Diversion Dam						
Site address or other description		Northwest side of facility						
Ownership	EID							
Land use type	Water Transport Facility							
Invaded vegetation type	Forest							
Gross Area	5,000 sq. ft.							
Disturbances & impacts	Facility Maintenance							
Associated species	Mixed Conifer, Black Oak, Black Cottonwood							
Environmental Conditions (e.g. soil conditions, exposure, etc.)								
Rocky, exposed								
Weed Information								
Weed genus and species	<i>Lathyrus latifolius</i>	<i>Verbascum thapsus</i>	<i>Leucanthemum vulgare</i>	<i>Cirsium vulgare</i>	<i>Bromus tectorum</i>			
Weed common name(s)	Sweet Pea	Woody Mullein	Ox-eye Daisy	Bull Thistle	Cheat grass			
Presence or Absence								
Treated	Present (not all species)	(physical removal - weed trimmer)	Present (not all species)					
Infested area	No	3,000 sq. ft.	<1%	<1%	1-5%			
Canopy Cover	5-25%	1-5%	Flowering	Flowering	Flowering			
Appearance	Flowering							
Distribution pattern	Scattered patchy	Clumpy						
Photo documentation	625,626,627,628		Weed Location					
Geographic location (ID)	41-08							
Coordinate system	Ca. State Plane Zone 2							
Datum	NAD83							
Location data accuracy	1-5m							
Location description	Disturbed area adjacent to Diversion Dam and river; also along road. 2011 Update: Overall increase; concentrated in boulder rip-rap; all the area up to edge of fish ladder.							

General Information		Site Information			
Collection date (mm/dd/yyyy) Observer name(s)	Ethan Koenigs	7/21/2011			
Site or facility name	Diversion Dam				
Site address or other description	Northeast side of facility				
Ownership	EID				
Land use type	Water Transport Facility				
Invaded vegetation type	Forest				
Gross Area	0.25 acres				
Disturbances & impacts	Facility Maintenance				
Associated species	Mixed Conifer, Black Oak				
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Very exposed, sunny.				
Weed Information		Weed Identification			
Weed genus and species	<i>Lathyrus latifolius</i>	<i>Verbascum thapsus</i>	<i>Centaurea solstitialis</i>	<i>Cirsium vulgare</i>	<i>Hirschfeldia incana</i>
Weed common name(s)	Sweet Pea (50%)	Woolly Mullein (<1%)	Star Thistle (<1%)	Bull Thistle	<i>Meliolotus officinalis</i>
				Mustard	Sweet Clover
				Present (not all species)	
Presence or Absence	Present (all)				
Treated	No				
Infested area	10,000 sq. ft.				
Canopy Cover	<1%	<1%	<1%	1-5%	<1%
Appearance	Flowering	New growth	New growth	Flowering	Seeding
Distribution pattern	Clumpy	Scattered patchy	Clumpy	Scattered patchy	Scattered patchy
Photo documentation	622, 623, 624				
Weed Location					
Geographic location (ID)	47-08				
Coordinate system	Ca. State Plane Zone 2				
Datum	NAD83				
Location data accuracy	1.5m				
Location description	Area adjacent to gravel turn around, near large boulders; mostly Sweet Pea. 2011 Update: Mostly sweet pea; needs hand work and riveg probably; few plants of CIVU and MEOF.				

General Information		ID: 48-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011
Site Information		
Site or facility name	El Dorado Canal	
Site address or other description	Beat 1	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	3750 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species	Black Oak, Ponderosa pine, Incense cedar, cinquefoil	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	shady	
Weed Information		
Weed Identification		
Weed genus and species	<i>Leucanthemum vulgare</i>	
Weed common name(s)	Ox-eye Daisy	
Present (not all species)		
Presence or Absence	Present (all)	
Treated	No	
Infested area	3,750 sq. ft.	
Canopy Cover	1-5%	
Appearance	Flowering	
Distribution pattern	Scattered even	
Photo documentation	631	
Weed Location		
Geographic location (ID)	48-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1.5m	
Location description	South side of canal at bridge 27d; near access road; 2011 Update: Slight increase in LEVU; overall size of occurrence in three years static.	

General Information		L10-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011
Observer name(s)		Site Information
Site or facility name	El Dorado Canal	
Site address or other description	Near spillway - Flume 9	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	1,000 sq. ft.	
Disturbances & impacts	Canal Maintenance	
Associated species	Douglas fir, Bracken fern, deer brush, incense cedar	
Environmental Conditions (e.g. soil conditions, exposure, etc.)		
Weed Information		Weed Identification
Weed genus and species	<i>Verbascum thapsus</i>	
Weed common name(s)	Woolly Mullein	
		Present (not all species)
Presence or Absence	Present (all)	
Treated	Yes	
Infested area	250 sq. ft.	
Canopy Cover	1-5%	
Appearance	Flowering	
Distribution pattern	Linear	
Photo documentation	645	
Weed Location		
Geographic location (ID)	L10-11	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1.5m	
Location description	West of Flume 9 before next spill.	

General Information			ID: L26-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011	
Observer name(s)			
Site or facility name	Access Road	The El Dorado Tunnel road	
Site address or other description			
Ownership			
Land use type			
Invaded vegetation type	Forest	Transportation Corridor	
Gross Area	3000 sq. ft.		
Disturbances & impacts	Roadside maintenance	Tunnel Construction	
Associated species			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Deer Brush, Black Oak, Big Leaf Maple, other weedy species	East-facing slope; very exposed	
Weed Information			
Weed Identification			
Weed genus and species	<i>Meliolotus officinalis</i>	<i>Hypericum perforatum</i>	<i>Bromus tectorum</i>
Weed common name(s)	Sweet Clover	Klamath Weed	Cheat grass
		Present (not all species)	Bromus diandrus
Presence or Absence	Yes	HYPE (absent)	Ripgut Brome
Treated		Needs Additional Treatment	
Infested area	3000 sq. ft.		
Canopy Cover	<1%		
Appearance	Flowering		1-5%
Distribution pattern	Clumpy	Seedling	Senesc.
Photo documentation	664, 665, 666, 667	Linear	Scattered even
Weed Location			
Geographic location (ID)	L26-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	<1m		
Location description	Upper Section of road from siphon exit to old canal bench. 2011 Update: Good control of MEOF; some MEOF still present near rocks and spring; BRDID2 and BRTI fairly heavy along shoulder.		

General Information		ID: L28-08	
Collection date (mm/dd/yyyy)	7/21/2011	Observer name(s)	Ethan Koenigs
Site or facility name	Access Road	Site Information	
Site address or other description	El Dorado tunnel road		
Ownership	Transportation Corridor		
Land use type	Forest		
Invaded vegetation type			
Gross Area	0.6 acres		
Disturbances & impacts	Roadside maintenance		
Associated species	Deer Brush, Black Oak, Big Leaf Maple, other weedy species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	East-facing slope		
Weed Information		Weed Identification	
Weed genus and species	<i>M. officinalis</i> , <i>T. arvensis</i>	<i>H. perforatum</i> , <i>B. tectorum</i>	<i>Bromus diandrus</i>
Weed common name(s)	Sweet Clover, Hedge Parsly	Klamath Weed, Cheat grass	Ripgut Brome
Present (not all species)			
Presence or Absence	Present (all)		
Treated	Yes		
Infested area	0.25 acres		
Canopy Cover	<1%	<1%	<1%
Appearance	Flowering	New growth	Seedling
Distribution pattern	Clumpy	Linear	Scattered even
Photo documentation	660, 661, 662, 663	Weed Location	
Geographic location (ID)	L28-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	<1m		
Location description	Lower section of road starting from L26-08 to near bridge over Alder Creek. 2011 Update: Sprayed roadside; good control of MEOF - dying; TOAR is flowering, increasing abundance, scattered even along shoulder of rd., there are also some dense patches. HYPE about same as 2010		

General Information		ID: L29-08	
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011	
Observer name(s)			
Site Information			
Site or facility name	Access Road		
Site address or other description	Camp 1 Road		
Ownership			
Land use type	Transportation Corridor		
Invaded vegetation type	Forest		
Gross Area	8,800 sq. ft.		
Disturbances & impacts	Roadside maintenance	Other man-made disturbance	
Associated species			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Ponderosa pine, black oak, deer brush rocky soil, northwest-facing slope		
Weed Information			
Weed Identification			
Weed genus and species	<i>Torilis arvensis</i> ,	<i>Melilotus officinalis</i>	<i>Bromus tectorum</i>
Weed common name(s)	Sweet Pea, Hedge Parsly,	Sweet Clover	Ripgut Bromo
		Klamath Weed	Cheat Grass
Present (not all species)			
Presence or Absence	Present (not all species)	Sweet Pea (absent)	
Treated	No		
Infested area	8800 sq. ft.		
Canopy Cover	<1%	<1%	1-5%
Appearance	New growth	Flowering	Senesc.
Distribution pattern	Scattered patchy	Linear	
Photo documentation	651, 652, 654		
Weed Location			
Geographic location (ID)	L29-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	<1m		
Location description	Upper half of Camp 1 road, primarily on down-slope side. 2011 Update: Moderate control along road; MEOF and BRDI at turnout near fork; few HYPE plants at turnout.		

General Information		ID: L30-08
Collection date (mm/dd/yyyy)	Ethan Koenigs,	7/21/2011
Observer name(s)		
Site or facility name	Access Road	Site Information
Site address or other description	Camp 1 road West fork	
Ownership	Transportation Corridor	
Land use type	Forest	
Invaded vegetation type	Roadside maintenance	
Gross Area	2500 sq. ft.	
Disturbances & impacts		
Associated species	Ponderosa Pine, Black Oak, Deer Brush	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Northwest-facing slope, partly shaded	
Weed Information		Weed Identification
Weed genus and species	Bromus tectorum	Melilotus officinalis
Weed common name(s)	Cheat grass	White Sweet Clover
		Present (not all species)
Presence or Absence	Present (not all species)	MEOF (absent)
Treated	No	
Infested area	2500 sq. ft.	
Canopy Cover	<1%	<1%
Appearance	Seeding	Flowering
Distribution pattern	Linear	Clumpy
Photo documentation	657, 658	
Weed Location		
Geographic location (ID)	L30-08	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	From fork in the road to the house. 2011 Update: Good control, especially on road shoulder; very little BRT; pretty good control of clump of LALA4; just a few HYPE down slope.	

General Information		ID: L32-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011
Observer name(s)		
Site or facility name	Access Road	Site Information
Site address or other description	Camp 1 road, 75A	
Ownership	EID	
Land use type	Transportation Corridor	
Invaded vegetation type	Forest	
Gross Area	2,500 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	Ponderosa Pine, Douglas Fir, Bracken Fern, Black Oak, Deer Brush, other weedy species.	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Northwest-facing slope, rocky soil, very exposed	
Weed Information		
Weed genus and species	<i>Meliolotus officinalis</i>	Weed Identification
Weed common name(s)	White Sweet Clover	<i>Bromus tectorum</i> Cheat grass
		<i>Verbascum thapsus</i> Woolly Mullein
		Present (not all species)
Presence or Absence	Present (not all species)	MEOF absent
Treated	Yes	
Infested area	2000 sq. ft.	
Canopy Cover	1-5%	<1%
Appearance	Flowering	Flowering
Distribution pattern	Seeding	
Photo documentation	Clumpy	Clumpy
	656	Scattered even
Weed Location		
Geographic location (ID)	L32-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	< 1m	
Location description	East fork of Camp 1 road, from clearing to gate at canal, on both sides of road. 2011 Update: Good control of MEOF; few VETH up near gate; treated after BRTE set seed; need to treat beyond end of road along fence/gate.	

General Information		ID: L33-08		
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011		
Site Information				
Site or facility name	El Dorado Canal			
Site address or other description	Beat 1			
Ownership				
Land use type	Water Transport Facility			
Invaded vegetation type	Forest			
Gross Area	16,000 sq. ft.			
Disturbances & impacts	Canal Maintenance	Historic Fire		
Associated species	Douglas Fir, Incense cedar, Bracken Fern, horsetail			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	NW exposure; mesic site; potential wet area or riparian zone			
Weed Information				
Weed Identification				
Weed genus and species	<i>Hypericum perforatum</i>	<i>Verbascum thapsus</i>		
Weed common name(s)	Klamath weed	Wooly Mullein		
Present (not all species)				
Presence or Absence	Present (all)	(BRTE present throughout burn area mostly outside fence)		
Treatment	No			
Infested area	1,000 sq. ft.			
Canopy Cover	<1%	1-5%		
Appearance	Flowering	Seeding		
Distribution pattern	Scattered even	Scattered even		
Photo documentation	646, 647, 648	Clumpy		
Weed Location				
Geographic location (ID)	L33-08			
Coordinate system	Ca. State Plane Zone 2			
Datum	NAD83			
Location data accuracy	1-5m			
Location description	North side of canal & north side of fence near solar powered monitoring station 3, Extend line back (E.) along canal approx. 300'. 2011 Update: HYPE is about the same; many new first year VETH; BRTE is increasing along canal within fence; one clump of CHJU.			

General Information		ID: L34-08		
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/21/2011		
Observer name(s)		Site Information		
Site or facility name	El Dorado Canal			
Site address or other description	Beat 1			
Ownership				
Land use type	Water Transport Facility			
Invaded vegetation type	Forest			
Gross Area	10,000 sq. ft.			
Disturbances & impacts	Canal Maintenance	Historic Fire		
Associated species	Bracken Fern, Thimbleberry			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	very exposed, northeast facing slope			
Weed Information				
Weed Identification				
Weed genus and species	<i>Bromus tectorum</i>	<i>Verbasium thapsus</i>		
Weed common name(s)	Cheat grass	Woolly Mullein		
	Present (not all species)			
Presence or Absence	Present (not all species)	No CHJU or CESO		
Treatment		No		
Infested area		10,000 sq. ft.		
Canopy Cover	5-25%	5-25%		
Appearance	Senesc.	New growth		
Distribution pattern	Linear	Clumpy		
Photo documentation	638, 639			
Weed Location				
Geographic location (ID)	L34-08			
Coordinate system	Ca. State Plane Zone 2			
Datum	NAD83			
Location data accuracy	1.5m			
Location description	Along canal bench north side. 2011 Upddate: Similar to 2010, all increasing; Starthistle returning; numerous new occurrences of multiple weeds; concentrated on east end of mapped line; consider not spraying but use hand treatment and re-seed outside fence to compete with weeds; CIVU and VETH primarily outside fence.			

General Information		ID: L35-08		
Collection date (mm/dd/yyyy)	Ethan Koenigs,	7/21/2011		
Site Information				
Site or facility name	El Dorado Canal			
Site address or other description	Beat 1			
Ownership				
Land use type	Water Transport Facility			
Invaded vegetation type				
Gross Area	Forest	3,000 sq. ft.		
Disturbances & impacts	Canal Maintenance	Historic Fire		
Associated species	Deer Brush, Big Leaf Maple, Black Oak, various weeds			
Environmental Conditions (e.g. soil conditions, exposure, etc.)	NE exposure; very exposed			
Weed Information				
Weed Identification				
Weed genus and species	<i>Chondrilla juncea</i>	<i>Bromus tectorum</i>		
Weed common name(s)	Rush Skeleton weed	Cheat Grass		
	Present (not all species)			
Presence or Absence	Present (all)			
Treatment	No			
Infested area		3,000 sq. ft.		
Canopy Cover	1-5%	25-50%		
Appearance	Flowering	Seedling		
Distribution pattern	Scattered patchy	Clumpy		
Photo documentation	635, 636, 637			
Weed Location				
Geographic location (ID)	L35-08			
Coordinate system	Other (specify):	State Plane		
Datum	NAD83			
Location data accuracy	1.5m			
Location description	Beginning just west of flume on north side of canal for approximately 200'. 2011 Update: Same at 2010; starting to get colonized by natives; avoid spray treatment; slight increase in CHJU and VETH; consider revegetation.			

**APPENDIX C**

**EID Weed Observation and Monitoring Form – Alder Diversion, Mill to Bull Tunnel  
Entrance**

<b>Photo Log</b>			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
668	L27-08	NW	Minor BRTE and other weeds
GPS photo L31-08	L31-08		
<b>Notes</b>			

General Information			ID: L27-08
Collection date (mm/dd/yyyy)	Ethan Koenigs,	Logan McCarthy	7/29/2011
Observer name(s)			Site Information
Site or facility name	El Dorado Canal		
Site address or other description	Short Section just before El Dorado Tunnel		
Ownership	EID		
Land use type	Water Transport Facility		
Invaded vegetation type	Forest		
Gross Area	750 sq. ft.		
Disturbances & impacts			
Associated species	Ponderosa Pine, Douglas fir, Black Oak, Deer Brush, Big Leaf Maple, other weedy species.		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	North facing slope no tree canopy.		
Weed Information			Weed Identification
Weed genus and species	<i>Hypericum perforatum</i>	<i>Melilotus officinalis</i>	<i>Bromus tectorum</i>
Weed common name(s)	Klamath Weed	White Sweet Clover	Cheat grass
Weed Description			Weed Description
Presence or Absence	Present (all)		
Treated	Yes		
Infested area	750 sq. ft.		
Canopy Cover	<1%	<1%	<1%
Appearance	Flowering	Flowering	New growth
Distribution pattern	Scattered patchy	Linear	
Photo documentation	668		
Weed Location			
Geographic location (ID)	L27-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	<1m		
Location description	Short section of canal from fence to flume. 2011 Update: Mostly cheat grass on edge of canal; many first year VETH plants.		

General Information		ID: L31-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	7/29/2011
Observer name(s)		Site Information
Site or facility name	Alder Creek Diversion & Pipeline	
Site address or other description	near siphon entrance	
Ownership		
Land use type	Water Transport Facility	
Invaded vegetation type	Forest	
Gross Area	7,000 sq. ft.	
Disturbances & impacts	Pipe Maintenance	
Associated species	P. Pine, Black Oak, Douglas Fir, Deer brush, Paint brush	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	west-facing exposure; very sunny; rocky soil	
Weed Information		Weed Identification
Weed genus and species	<i>Bromus tectorum</i>	
Weed common name(s)	Cheat Grass	
		Present (not all species)
Presence or Absence	Present (all)	
Treated	Yes	Sprayed
Infested area		3,500 sq. ft.
Canopy Cover	1-5%	
Appearance	Seedling	Senesc.
Distribution pattern	Scattered even	
Photo documentation	GPS photo L31-08	
Weed Location		
Geographic location (ID)	L31-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1.5m	
Location description	Alder diversion pipe; beginning at siphon entrance & extending for about 350'. 2011 Update: About the same as 2010; treatment too late for cheat grass.	

**APPENDIX C****EID Weed Observation and Monitoring Form – Silver Lake /Caples Lake Area**

<b>Photo Log</b>			
Photo #	GPS Waypoint or feature #	Bearing or Direction	Feature/Notes
728/729	11-09	SE/S	Silver Lake - VETH at S. side of day-use boat ramp parking area
730-732	11-09	SW/SW	Silver Lake - close-up of VETH patch near lake
733	44-08	N	Silver Lake –Road to Ferguson Pt. - good weed control
734/735	44-08	NW/SW	Silver Lake –Road to Ferguson Pt. - dying VETH and CIVU
736	03-11	E	MEOF - near highway 88 & Caples Spillway
737	49-08	SW	Caples lake, near spillway; good control of weeds along shore
738/739	A01-11	S-SW	HYPE along face of Caples main dam; low density scattered
743	04-11	S	Dying MEOF in planter; Caples day-use boat launch
744	04-11	W	Scattered MEOF ; some dying in Day-use planter
745	04-11	SE	VETH adjacent to w. side of parking lot in Day-use picnic area
<b>Notes</b>			

General Information		ID: 03-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	8/10/2011
Observer name(s)		
Site or facility name	Caples Lake	Site Information
Site address or other description	Highway 88 and Caples spillway parking area	
Ownership	Caltrans / EID	
Land use type	Transportation Corridor	
Invaded vegetation type	riparian	
Gross Area	200 sq. ft.	
Disturbances & impacts	Roadside maintenance	
Associated species	lodgepole, yellow willow, associated herbaceous riparian	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	roadside riparian/ very open, no tree canopy	
Weed Information		Weed Identification
Weed genus and species	<i>Meliolotus alba</i>	
Weed common name(s)	Sweet clover	Present (not all species)
Presence or Absence	Present (all)	
Treated	No	
Infested area	200 sq. ft.	
Canopy Cover	1-5%	
Appearance	Flowering	
Distribution pattern	Clumpy	
Photo documentation	736	
Weed Location		
Geographic location (ID)	03-11	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1.5m	
Location description	Caples Lake parking area at Spillway, west end of lot near highway - may be with Cal Trans ROW. Small patch of MEOF	

General Information		ID: 04-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	8/10/2011
Observer name(s)		
Site or facility name	Caples Lake	Site Information
Site address or other description		
Ownership		
Land use type	Water Storage Facility	
Invaded vegetation type	Forest	
Gross Area	3350 sq. ft.	
Disturbances & impacts	Facility Maintenance	Recently planted with native vegetation
Associated species		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	lodgepole, aspen, juniper, red fir Recently constructed / landscaped day-use facility	
Weed Information		Weed Identification
Weed genus and species	<i>Meliolotus alba</i>	<i>Verbascum thapsus</i>
Weed common name(s)	Sweet clover	Wooly Mullein
		Present (not all species)
Presence or Absence	Present (all)	
Treated	Yes	
Infested area	3350 sq. ft.	
Canopy Cover	<1%	<1%
Appearance	New growth	New growth
Distribution pattern	Scattered patchy	Scattered patchy
Photo documentation	743 - 745	
Weed Location		
Geographic location (ID)	4 points within 04-11	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1-5m	Weeds are located at several locations within the Day-use area; primarily within the landscape "islands", but also with within the picnic area between the shore and parking area. A few wooly mullein at Highway ROW and entrance. Weeds mostly in planted areas. 80-90% of weeds sprayed recently.
Location description		

General Information		ID: 11-09	
Collection date (mm/dd/yyyy)	Ethan Koenigs	8/10/2011	
Observer name(s)			
Site or facility name	Silver Lake	Site Information	
Site address or other description	Kays Resort		
Ownership	Water Storage Facility		
Land use type	Forest		
Invaded vegetation type			
Gross Area	10,000 sq. ft.		
Disturbances & impacts	Canal Maintenance	Graded gravel area SW of resort	
Associated species	Lodgepole Pine, Red Fir, Willow, Sedges		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Close to lake (50ft).		
Weed Information		Weed Identification	
Weed genus and species	<i>Verbascum thapsus</i>		
Weed common name(s)	Woolly Mullein		
Presence or Absence	Yes	Present (not all species)	
Treated	No		
Infested area	5,000 sq. ft.		
Canopy Cover	1-5%		
Appearance	New growth	Flowering	
Distribution pattern	Scattered patchy		
Photo documentation	728 - 732		
Weed Location			
Geographic location (ID)	11-09		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	1.5m		
Location description	New boat Launch facility at Silver Lake. 2011 update: Increasing Wooly Mullein, lots of first year plants, more around parking lot edge. Recommend hand treatment.		

General Information		ID: 44-08	
Collection date (mm/dd/yyyy)	Ethan Koenigs	8/10/2011	
Observer name(s)			
Site or facility name	Silver Lake	Site Information	
Site address or other description	Adjacent to dam		
Ownership	Water Storage Facility		
Land use type	Forest		
Invaded vegetation type			
Gross Area	250 sq. ft.		
Disturbances & impacts	Roadside maintenance	Facility Maintenance	
Associated species	Lodgepole Pine, Red Fir, Pennyroyal, Mountain White Thorn		
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Flat area near lake; very little canopy cover.		
Weed Information		Weed Identification	
Weed genus and species	<i>Verbascum thapsus</i>	<i>Cirsium vulgare</i>	
Weed common name(s)	Woolly Mullein	Bull Thistle	
Presence or Absence	Yes	Present (not all species)	
Treated	Yes		
Infested area	50 sq. ft.		
Canopy Cover	<1%		
Appearance	New growth	Flowering	
Distribution pattern	Scattered patchy	Scattered patchy	
Photo documentation	733 - 735		
Weed Location			
Geographic location (ID)	44-08		
Coordinate system	Ca. State Plane Zone 2		
Datum	NAD83		
Location data accuracy	1.5m		
Location description	Northwest side of dam at intersection with Hwy. 88 and road to Ferguson Point. Treated with herbicide. Effective control.		

General Information		ID: 49-08
Collection date (mm/dd/yyyy)	Ethan Koenigs	8/10/2011
Observer name(s)		
Site or facility name	Caples Lake	Site Information
Site address or other description	Auxillary Dam	
Ownership		
Land use type	Water Storage Facility	
Invaded vegetation type	growing from rip rap	
Gross Area	1000 sq. ft.	
Disturbances & impacts	Dam	
Associated species	Sage brush, Rabbit brush, Phlox	
Environmental Conditions (e.g. soil conditions, exposure, etc.)	Fully exposed gravelly, rocky soil.	
Weed Information		Weed Identification
Weed genus and species	<i>Verbascum thapsus</i>	
Weed common name(s)	Wooly Mullein	Present (not all species)
Presence or Absence	Present (all)	
Treated	Yes	
Infested area	1000 sq. ft.	
Canopy Cover	<1%	
Appearance	Dying	
Distribution pattern	Scattered even	Linear
Photo documentation	737	Weed Location
Geographic location (ID)	49-08	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1.5m	Along interior face of dam, near water. Very minor occ. Effectively spot treated with herbicide; including several other scattered plants nearby.
Location description		

General Information		ID: A01-11
Collection date (mm/dd/yyyy)	Ethan Koenigs	8/10/2011
Observer name(s)		
Site or facility name	Caples Lake	Caples Dam
Ownership	EID	
Land use type	Water Storage Facility	Ruderal
Invaded vegetation type	Facility Maintenance	2.5 acres
Gross Area		
Disturbances & impacts		
Associated species		sagebrush, penstemon, yarrow, currants, aster
Environmental Conditions (e.g. soil conditions, exposure, etc.)		dam fill
Weed Information		Weed Identification
Weed genus and species	<i>Hypericum perforatum</i>	
Weed common name(s)	Klamath weed	
	Present (not all species)	
Presence or Absence	Present (all)	
Treated	No	
Infested area	2.5 acres	
Canopy Cover	1-5%	
Appearance	New growth	
Distribution pattern	Scattered even	
Photo documentation	738, 739	from E of dam looking west
Weed Location		
Geographic location (ID)	A01-11	
Coordinate system	Ca. State Plane Zone 2	
Datum	NAD83	
Location data accuracy	1.5m	
Location description	Scattered along face of dam. Because of low density and diverse local vegetation, hand pulling or no treatment recommended -weed is naturalized.	

## 2011 Data Sheet Index

Date	Locations
<b>June 22</b>	Upper penstock (partial); Powerhouse Rd., Forebay Res., Rd. 93
<b>June 23</b>	Highway Cut Rd. (10N40G), Rds. 81-84, 11N02Y
<b>June 29</b>	El Dorado Canal Beats 4 and 5
<b>July 1</b>	Camp 2 and 3 roads, 10N08Y, Rds.87-89
<b>July 7</b>	El Dorado Canal Beats 2, 3 and partial 4
<b>July 14</b>	Lower penstock, partial upper penstock, partial Forebay Res., Moon Lane, Bend Court
<b>July 21</b>	El Dorado Canal Beat 1, Camp 1 rds. (74 and 75),
<b>July 29</b>	Alder Creek diversion, Mill to Bull tunnel entrance
<b>August 10</b>	Caples Lake and Silver Lake

**APPENDIX D**  
**Eldorado National Forest Noxious Weeds List**

## Eldorado National Forest Noxious Weed List

List A. Highly invasive weed species known or suspected (\*) to occur on the Eldorado National Forest

<i>Aegilops triuncialis</i>	barbed goatgrass
<i>Bromus tectorum</i>	cheat grass
<i>Cardus nutans*</i>	musk thistle
<i>Carduus pycnocephalus</i>	Italian thistle
<i>Centaurea maculata</i>	spotted knapweed
<i>Centaurea solstitialis</i>	yellow starthistle
<i>Cirsium arvense*</i>	Canada thistle
<i>Chondrilla juncea</i>	rush skeletonweed
<i>Cytisus scoparius</i>	Scotch broom
<i>Genistia monspellensis</i>	French broom
<i>Lepidium latifolium</i>	tall whitetop /perennial pepperweed
<i>Linaria genistifolia ssp. dalmatica*</i>	dalmation toadflax
<i>Lythrum salicaria</i> (added 12/26/07)	purple loosestrife
<i>Spartium junceum</i>	Spanish broom
<i>Taeniatherum caput-medusae</i>	medusahead grass

List B. A list of other exotic or noxious weeds that may occur on the Eldorado National Forest that currently are not believed to be as aggressive as those in list A

<i>Acroptilon repens</i> ( <i>Centaurea repens</i> )	Russian knapweed
<i>Ailanthus altissima</i>	Chinese tree of heaven
<i>Bromus diandrus</i>	ripgut brome
<i>Cardaria chalapense</i>	small (lens podded) whitetop
<i>Cardaria draba</i>	heart podded whitetop
<i>Centaurea diffusa</i>	diffuse (white) knapweed
<i>Centaurea melitonensis</i>	tocalote
<i>Cirsium vulgare</i>	bull thistle
<i>Conium maculatum</i>	poison hemlock
<i>Euphorbia esula</i> *	leafy spurge
<i>Euphorbia oblongata</i>	oblong spurge
<i>Festuca arundinaceae</i>	tall fescue
<i>Foeniculum vulgare</i>	fennel
<i>Hirschfeldia incana</i> (added 7/03)	mustard
<i>Hypericum perforatum</i>	Klamathweed
<i>Leucanthemum vulgare</i>	ox-eye daisy
<i>Lathyrus latifolius</i>	perennial sweet pea
<i>Lychnis coronaria</i>	rose campion / mullein pink
<i>Meliolotus alba</i>	white sweet clover
<i>Meliolotus officinalis</i>	yellow sweet clover
<i>Onopordum acanthium</i> (added 8/16/04)	Scotch thistle
<i>Rubus discolor</i>	Himalayan blackberry
<i>Salsola tragus</i>	Russian thistle / tumbleweed
<i>Silybum marianum</i> (added 9/25/03)	milk thistle
<i>Sisymbrium altissimum</i> (added 12/26/03)	Jim Hill or tumble mustard
<i>Tamarix chinensis</i> *	tamarisk / salt cedar
<i>Torilis arvensis</i> (added 7/2/03)	hedge parsley
<i>Verbascum thapsus</i>	woolly mullein